English	~	Search Microchip
		Search Data Sheets

PRODUCTS **APPLICATIONS** DESIGN SUPPORT TRAINING SAMPLE & BUY ABOUT US Contact Us myMicrochip Login

Product Change Notification - SYST-15JBDQ546 (Printer Friendly)

Date: 18 Dec 2015 Affected CPNs: **7.**

Notification subject: ERRATA - MCP7941X Family Silicon Errata Errata Document Revision

Notification text: SYST-15JBDQ546

Microchip has released a new DeviceDoc for the MCP7941X Family Silicon Errata of devices. If you are using one of these devices please

read the document located at MCP7941X Family Silicon Errata.

Notification Status: Final

Description of Change: Added silicon issue 4 (spurious alarm interrupts when matching on minutes).

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity Change Implementation Status: Complete Date Document Changes Effective: 18 Dec 2015

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): MCP7941X Family Silicon Errata

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."









Contact Us Legal Investors Careers

Products Applications Design Support Training Sample & Buy About Us

©Copyright 1998-2015 Microchip Technology Inc. All rights reserved. Shanghai ICP Recordal No.09049794