



PRODUCT BULLETIN

Generic Copy

ISSUE DATE: 17-Oct-2013
NOTIFICATION: 15823
TITLE: KINETIS K, L, COLDFIRE+ ERRATA UPDATES
EFFECTIVE DATE: 18-Oct-2013

DEVICE(S)

MPN
CRTOUCHB10VFM
MCF51JF128VHS
MCF51JF128VLH
MCF51JF32VFM
MCF51JF32VHS
MCF51JF64VHS
MCF51JF64VLF
MCF51JU128VHS
MCF51JU128VLH
MCF51JU32VFM
MCF51JU32VHS
MCF51JU64VHS
MCF51JU64VLF
MCF51QM128VHS
MCF51QM128VHSR
MCF51QM128VLH
MCF51QM128VLHR
MCF51QM32VFM
MCF51QM32VHS
MCF51QM64VHS
MCF51QM64VLF
MCF51QU128VHS
MCF51QU128VLH
MCF51QU128VLHR
MCF51QU32VFM
MCF51QU32VHS
MCF51QU64VHS

MCF51QU64VLF

MK10DN128VFM5

MK10DN128VFT5

MK10DN128VLF5

MK10DN128VLF5R

MK10DN128VLH5

MK10DN128VLH5R

MK10DN128VMP5

MK10DN32VFM5

MK10DN32VFT5

MK10DN32VLF5

MK10DN32VLH5

MK10DN32VMP5

MK10DN512VLK10

MK10DN512VLL10

MK10DN512VLQ10

MK10DN512VMC10

MK10DN512VMC10R

MK10DN512VMD10

MK10DN512ZVLK10

MK10DN512ZVLK10R

MK10DN512ZVLL10

MK10DN512ZVLL10R

MK10DN512ZVLQ10

MK10DN512ZVMC10

MK10DN512ZVMC10R

MK10DN512ZVMD10

MK10DN64VFM5

MK10DN64VFT5

MK10DN64VLF5

MK10DN64VLH5

MK10DN64VMP5

MK10DX128VFM5

MK10DX128VFT5

MK10DX128VLF5

MK10DX128VLH5

MK10DX128VLH7

MK10DX128VLK7

MK10DX128VLK7R

MK10DX128VLL7

MK10DX128VLQ10

MK10DX128VMC7

MK10DX128VMD10

MK10DX128VMP5

MK10DX128ZVMD10

MK10DX256VLH7

MK10DX256VLK7

MK10DX256VLK7R

MK10DX256VLL7

MK10DX256VLQ10

MK10DX256VMC7

MK10DX256VMD10

MK10DX256ZVLQ10

MK10DX256ZVLQ10R

MK10DX256ZVMD10

MK10DX32VFM5

MK10DX32VFT5

MK10DX32VLF5

MK10DX32VLH5

MK10DX32VMP5

MK10DX64VFM5

MK10DX64VFT5

MK10DX64VLF5

MK10DX64VLH5

MK10DX64VLH7

MK10DX64VLK7

MK10DX64VLK7R

MK10DX64VMC7

MK10DX64VMP5

MK11DN512VLK5

MK11DN512VMC5

MK11DX128VLK5

MK11DX128VMC5

MK11DX256VLK5

MK11DX256VMC5

MK12DN512VLH5

MK12DN512VLK5

MK12DN512VMC5

MK12DX128VLF5
MK12DX128VLH5
MK12DX128VLK5
MK12DX128VMC5
MK12DX256VLF5
MK12DX256VLH5
MK12DX256VLK5
MK12DX256VMC5
MK20DN128VFM5
MK20DN128VFT5
MK20DN128VLF5
MK20DN128VLH5
MK20DN128VMP5
MK20DN32VFM5
MK20DN32VFT5
MK20DN32VLF5
MK20DN32VLH5
MK20DN32VMP5
MK20DN512VLK10
MK20DN512VLL10
MK20DN512VLQ10
MK20DN512VMC10
MK20DN512VMD10
MK20DN512ZAB10R
MK20DN512ZCAB10R
MK20DN512ZVLK10
MK20DN512ZVLL10
MK20DN512ZVLQ10
MK20DN512ZVLQ10R
MK20DN512ZVMC10
MK20DN512ZVMC10R
MK20DN512ZVMD10
MK20DN64VFM5
MK20DN64VFT5
MK20DN64VLF5
MK20DN64VLH5
MK20DN64VMP5
MK20DX128VFM5
MK20DX128VFT5

MK20DX128VLF5
MK20DX128VLH5
MK20DX128VLH7
MK20DX128VLK7
MK20DX128VLL7
MK20DX128VLQ10
MK20DX128VMC7
MK20DX128VMP5
MK20DX128ZVLQ10
MK20DX256VLH7
MK20DX256VLK10
MK20DX256VLK7
MK20DX256VLK7R
MK20DX256VLL10
MK20DX256VLL7
MK20DX256VLQ10
MK20DX256VLQ10R
MK20DX256VMC10
MK20DX256VMC7
MK20DX256VMD10
MK20DX256ZVLK10
MK20DX256ZVLL10
MK20DX256ZVLQ10
MK20DX256ZVMC10
MK20DX256ZVMD10
MK20DX32VFM5
MK20DX32VFT5
MK20DX32VLF5
MK20DX32VLH5
MK20DX32VMP5
MK20DX64VFM5
MK20DX64VFT5
MK20DX64VLF5
MK20DX64VLH5
MK20DX64VLH7
MK20DX64VLK7
MK20DX64VMC7
MK20DX64VMP5
MK21DN512VLK5

MK21DN512VMC5

MK21DX128VLK5

MK21DX128VMC5

MK21DX256VLK5

MK21DX256VMC5

MK21FN1M0VLQ12

MK21FN1M0VMC12

MK21FN1M0VMD12

MK21FX512VLQ12

MK21FX512VMC12

MK21FX512VMD12

MK22DN512VLH5

MK22DN512VLK5

MK22DN512VMC5

MK22DX128VLF5

MK22DX128VLH5

MK22DX128VLK5

MK22DX128VMC5

MK22DX256VLF5

MK22DX256VLH5

MK22DX256VLK5

MK22DX256VMC5

MK22FN1M0VDC12

MK22FN1M0VLH12

MK22FN1M0VLK12

MK22FN1M0VLL12

MK22FN1M0VLQ12

MK22FN1M0VMC12

MK22FN1M0VMD12

MK22FX512VLH12

MK22FX512VLK12

MK22FX512VLL12

MK22FX512VLQ12

MK22FX512VMC12

MK22FX512VMD12

MK30DN512VLL10

MK30DN512VLQ10

MK30DN512ZVLK10

MK30DN512ZVLQ10

MK30DN512ZVLQ10R
MK30DX128VLH7
MK30DX128VLK7
MK30DX128VLL7
MK30DX128VMC7
MK30DX256VLH7
MK30DX256VLK7
MK30DX256VLL7
MK30DX256VLQ10
MK30DX256VMC7
MK30DX256ZVLQ10
MK30DX64VLH7
MK30DX64VLK7
MK30DX64VLK7R
MK30DX64VMC7
MK40DN512VLK10
MK40DN512VLL10
MK40DN512VLQ10
MK40DN512VMD10
MK40DN512ZVLL10
MK40DN512ZVLQ10
MK40DN512ZVMD10
MK40DX128VLH7
MK40DX128VLK7
MK40DX128VLL7
MK40DX128VMC7
MK40DX128VMD10
MK40DX128ZVLQ10
MK40DX256VLH7
MK40DX256VLK7
MK40DX256VLL7
MK40DX256VLQ10
MK40DX256VMC7
MK40DX256VMD10
MK40DX256ZVLQ10
MK40DX256ZVMD10
MK40DX64VLH7
MK40DX64VLK7

MK40DX64VMC7

MK50DN512CLL10

MK50DN512CLQ10

MK50DN512CMC10

MK50DN512CMD10

MK50DN512CMD10R

MK50DN512ZCLL10

MK50DN512ZCLQ10

MK50DX128CLH7

MK50DX128CLH7R

MK50DX128CLK7

MK50DX128CLL7

MK50DX128CMC7

MK50DX256CLK10

MK50DX256CLK7

MK50DX256CLL10

MK50DX256CLL7

MK50DX256CMC10

MK50DX256CMC7

MK50DX256CMD10

MK50DX256ZCLL10

MK50DX256ZCLQ10

MK51DN256CMD10

MK51DN256ZCMD10

MK51DN512CLL10

MK51DN512CLQ10

MK51DN512CMC10

MK51DN512CMD10

MK51DN512ZCLL10

MK51DN512ZCLQ10

MK51DN512ZCMC10

MK51DX128CLH7

MK51DX128CLK7

MK51DX128CMC7

MK51DX256CLK10

MK51DX256CLK7

MK51DX256CLL10

MK51DX256CLL7

MK51DX256CMC10

MK51DX256CMC7

MK51DX256ZCLL10

MK51DX256ZCMC10

MK52DN512CLQ10

MK52DN512CMD10

MK52DN512ZCLQ10

MK52DN512ZCMD10

MK53DN512CLQ10

MK53DN512CMD10

MK53DN512ZCLQ10

MK53DN512ZCMD10

MK53DX256CLQ10

MK53DX256CMD10

MK53DX256ZCLQ10

MK60DN256VLL10

MK60DN256VLL10R

MK60DN256VLQ10

MK60DN256VMD10

MK60DN256ZVLL10

MK60DN256ZVLQ10

MK60DN512VLL10

MK60DN512VLL10R

MK60DN512VLQ10

MK60DN512VMC10

MK60DN512VMD10

MK60DN512ZAB10R

MK60DN512ZCAB10R

MK60DN512ZVLL10

MK60DN512ZVLQ10

MK60DN512ZVLQ10R

MK60DN512ZVMC10

MK60DN512ZVMD10

MK60DX256VLL10

MK60DX256VLQ10

MK60DX256VMC10

MK60DX256VMD10

MK60DX256ZVLL10

MK60DX256ZVLQ10

MK60DX256ZVMC10

MK60DX256ZVMD10

MKL02Z16VFG4

MKL02Z16VFG4R

MKL02Z16VFK4

MKL02Z16VFM4

MKL02Z32CAF4R

MKL02Z32VFG4

MKL02Z32VFG4R

MKL02Z32VFK4

MKL02Z32VFK4R

MKL02Z32VFM4

MKL02Z8VFG4

MKL02Z8VFG4R

MKL04Z16VFK4

MKL04Z16VFM4

MKL04Z16VLC4

MKL04Z16VLF4

MKL04Z32VFK4

MKL04Z32VFM4

MKL04Z32VFM4R

MKL04Z32VLC4

MKL04Z32VLC4R

MKL04Z32VLF4

MKL04Z32VLF4R

MKL04Z8VFK4

MKL04Z8VFM4

MKL04Z8VLC4

MKL05Z16VFK4

MKL05Z16VFM4

MKL05Z16VLC4

MKL05Z16VLF4

MKL05Z32VFK4

MKL05Z32VFM4

MKL05Z32VFM4R

MKL05Z32VLC4

MKL05Z32VLF4

MKL05Z8VFK4

MKL05Z8VFM4

MKL05Z8VLC4

MKL14Z32VFM4

MKL14Z32VFT4

MKL14Z32VLH4

MKL14Z32VLK4

MKL14Z64VFM4

MKL14Z64VFM4R

MKL14Z64VFT4

MKL14Z64VLH4

MKL14Z64VLK4

MKL15Z128VFM4

MKL15Z128VFT4

MKL15Z128VLH4

MKL15Z128VLH4R

MKL15Z128VLK4

MKL15Z32VFM4

MKL15Z32VFT4

MKL15Z32VLH4

MKL15Z32VLK4

MKL15Z64VFM4

MKL15Z64VFM4R

MKL15Z64VFT4

MKL15Z64VLH4

MKL15Z64VLK4

MKL16Z128VFM4

MKL16Z128VFT4

MKL16Z128VLH4

MKL16Z128VLH4R

MKL16Z256VLH4

MKL16Z256VMP4

MKL16Z32VFM4

MKL16Z32VFT4

MKL16Z32VLH4

MKL16Z64VFM4

MKL16Z64VFT4

MKL16Z64VLH4

MKL16Z64VLH4R

MKL24Z32VFM4

MKL24Z32VFT4

MKL24Z32VLH4
MKL24Z32VLK4
MKL24Z64VFM4
MKL24Z64VFT4
MKL24Z64VLH4
MKL24Z64VLK4
MKL25Z128VFM4
MKL25Z128VFT4
MKL25Z128VLH4
MKL25Z128VLK4
MKL25Z32VFM4
MKL25Z32VFT4
MKL25Z32VLH4
MKL25Z32VLK4
MKL25Z64VFM4
MKL25Z64VFT4
MKL25Z64VLH4
MKL25Z64VLK4
MKL26Z128VFM4
MKL26Z128VFT4
MKL26Z128VLH4
MKL26Z128VLL4
MKL26Z128VMC4
MKL26Z256VLH4
MKL26Z256VLL4
MKL26Z256VMC4
MKL26Z256VMP4
MKL26Z32VFM4
MKL26Z32VFT4
MKL26Z32VLH4
MKL26Z64VFM4
MKL26Z64VFT4
MKL26Z64VLH4
MKL34Z64VLH4
MKL34Z64VLL4
MKL36Z128VLH4
MKL36Z128VLL4
MKL36Z128VMC4

MKL36Z256VLH4

MKL36Z256VLL4

MKL36Z256VLL4R

MKL36Z256VMC4

MKL36Z256VMP4

MKL36Z64VLH4

MKL36Z64VLL4

MKL46Z128VLH4

MKL46Z128VLL4

MKL46Z128VMC4

MKL46Z256VLH4

MKL46Z256VLL4

MKL46Z256VMC4

MKL46Z256VMP4

PCK22FN1M3VMC12

PCRTOUCHB10VFM

PK10DN32VFM5

PK10DN512VLK10

PK10DN512VLL10

PK10DN512VLQ10

PK10DN512VMC10

PK10DN512VMD10

PK10DX128VFM5

PK10DX128VFT5

PK10DX128VLF5

PK10DX128VLH5

PK10DX128VMP5

PK10DX256VLH7

PK10DX256VLK7

PK10DX256VLL7

PK10DX256VLQ10

PK10DX256VMD10

PK10X256VLQ100

PK12DN512VLH5

PK12DX256VLF5

PK20DN128VLH5

PK20DN128VMP5

PK20DN512VLK10

PK20DN512VMD10

PK20DN512ZVLK10

PK20DX128CMD5

PK20DX128VFM5

PK20DX128VFT5

PK20DX128VLF5

PK20DX128VLH5

PK20DX128VMP5

PK20DX256VLH7

PK20DX256VLK10

PK20DX256VLK7

PK20DX256VLL7

PK20N512VLL100

PK21DN512VLK5

PK21DN512VMC5

PK21DX128VMC5

PK21DX256VLK5

PK21DX256VMC5

PK21FN1M0VMC10

PK21FN1M0VMD10

PK21FX512VMD10

PK22DN512VLH5

PK22DN512VLK5

PK22DN512VMC5

PK22DX256VLF5

PK22DX256VLH5

PK22DX256VLK5

PK22DX256VMC5

PK22FN1M0VDC12

PK22FN1M0VLH10

PK22FN1M0VLK10

PK22FN1M0VLL10

PK22FN1M0VLQ10

PK22FN1M0VMC10

PK22FN1M0VMC12

PK30DN512VLQ10

PK30DX128VLL7

PK30DX256VLH7

PK30DX256VLK7

PK30DX256VLL10

PK30DX256VLL7

PK40DN512VLK10

PK40DN512VLL10

PK40DN512VLQ10

PK40DN512VMC10

PK40DN512VMD10

PK40DN512ZVLL10

PK40DX256VLH7

PK40DX256VLK7

PK40DX256VLL7

PK40DX256VLQ10

PK40DX256VMD10

PK50DN512CMD10

PK50DX128CLH7

PK50DX256CLK7

PK50DX256CLL10

PK50DX256CLL7

PK50DX256CMC10

PK50DX256CMD10

PK51DN512CLL10

PK51DX128CLH7

PK51DX256CLK7

PK51DX256CLL7

PK51DX256CMC10

PK52DN512CMD10

PK53DN512CMD10

PK53DX256CLQ10

PK53DX256CMD10

PK60DN512VLL10

PK60DN512VLQ10

PK60DN512VMD10

PK60DX256VLL10

PK60DX256VLQ10

PK60DX256VMC10

PK60DX256VMD10

PKL02Z16VFG4

PKL02Z32VFG4

PKL02Z32VFK4

PKL02Z32VFM4
PKL05Z32VFK4
PKL05Z32VFM4
PKL05Z32VLC4
PKL05Z32VLF4
PKL15Z128CAD4R
PKL15Z128LCAD4R
PKL15Z128VFM4
PKL15Z128VFT4
PKL15Z128VLH4
PKL15Z128VLK4
PKL16Z128VFM4
PKL16Z128VFT4
PKL16Z128VLH4
PKL16Z256VMP4
PKL17Z32CAL4R
PKL25Z128VFM4
PKL25Z128VFT4
PKL25Z128VLH4
PKL25Z128VLK4
PKL26Z128CAL4R
PKL26Z128VFM4
PKL26Z128VFT4
PKL26Z128VLH4
PKL26Z128VLL4
PKL26Z256VLH4
PKL26Z256VLL4
PKL26Z256VMC4
PKL26Z256VMP4
PKL36Z256VLH4
PKL36Z256VMP4
PKL46Z256VLL4
PKL46Z256VMC4

AFFECTED CHANGE CATEGORIES

- ERRATA

DESCRIPTION OF CHANGE

The Kinetis K, L, and ColdFire+ errata documentation has been updated to include a new erratum that has been identified. The updated versions have been added to the freescale.com website at:

http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_4N30D.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_8N30D.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_4N22D.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS72MHZ_2N36B.pdf
http://cache.freescale.com/files/32bit/doc/errata/KINETIS_0N89E.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_1N89E.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_2N03G.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS50MHZ_1N86B.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS50MHZ_3N86B.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_L_2N97F.pdf
http://cache.freescale.com/files/32bit/doc/errata/KINETIS_L_1N96F.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS_L_0N40H.pdf
http://cache.freescale.com/files/32bit/doc/errata/COLDFIREPLUS_4N27B.pdf
http://cache.freescale.com/files/32bit/doc/errata/COLDFIREPLUS_2N27B.pdf
http://cache.freescale.com/files/32bit/doc/errata/KINETIS_L_0N33H.pdf
http://cache.freescale.com/files/microcontrollers/doc/errata/KINETIS72MHZ_1N36B.pdf

6665 Operating requirements: Limitation of the device operating range

REASON FOR CHANGE

The errata documentation for the Kinetis K, L, and ColdFire+ devices have been updated.

ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

There have been no changes made to the current production devices. The erratum describes existing conditions identified on current production devices. There are potential hardware implications.

NOTE:

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a [Service Request](#)

For sample inquiries - please go to www.freescale.com

QUAL DATA AVAILABILITY DATE: 25-Jul-2013

QUALIFICATION STATUS: COMPLETED

QUALIFICATION PLAN:

N/A

RELIABILITY DATA SUMMARY:

N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

N/A

CHANGED PART IDENTIFICATION:

N/A

ATTACHMENT(S):

External attachment(s) FOR this notification can be viewed AT:

[15823_COLDFIREPLUS_2N27B.pdf](#)[15823_COLDFIREPLUS_4N27B.pdf](#)[15823_KINETIS_0N89E.pdf](#)[15823_KINETIS_1N89E.pdf](#)[15823_KINETIS_2N03G.pdf](#)[15823_KINETIS_L_0N33H.pdf](#)[15823_KINETIS_L_1N96F.pdf](#)[15823_KINETIS_L_2N97F.pdf](#)[15823_KINETIS72MHZ_1N36B.pdf](#)[15823_KINETIS_4N22D.pdf](#)[15823_KINETIS_4N30D.pdf](#)[15823_KINETIS_8N30D.pdf](#)[15823_KINETIS_50MHZ_1N86B.pdf](#)[15823_KINETIS_50MHZ_3N86B.pdf](#)[15823_KINETIS_L_0N40H.pdf](#)[15823_KINETIS72MHZ_2N36B.pdf](#)