

## PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS **20210728-3**

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE:  **NA**  **EMEA**  **LATAM**  **AP** Jul-21

IMPACTED REGIONS:  **DISCONTINUATION**

REASON FOR CHANGE:  **OTHER**

### DESCRIPTION OF CHANGE: (Required)

NetKey punchdown-style jack modules are undergoing a modification to the manufacturing process. External form and fit will be unchanged and visual appearance will be virtually identical. Since this is a running update, there is no change to the part number or product specifications at this time. This Product Change Notification is intended to be informative; no further action need be taken.

Affected products include NetKey punchdown-style jack modules in Category 6A (NK6X88M\*\*), Category 6 (NK688M\*\*), and Category 5e (NKP5E88M\*\*).

Details of changes are described below:

- The material for the front housing is being changed from an ABS to a polycarbonate resin to provide a maximum operating temperature of 75°C for the jack modules. Panduit has worked extensively to match as closely as possible the appearance of the existing material however very minor differences in color shade or surface gloss may be noticeable on some jack colors under certain lighting conditions.
- Minor internal changes have been made and will result in a slight cosmetic difference at the port opening of the jack modules (see images below).

The change will roll out to NetKey jack module product lines and global warehouses over time, beginning on the availability date below and continuing throughout 2021.

Photos/Drawing (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

### DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	8	1
Old product discontinuation date*			

### CUSTOMER SERVICE CONTACTS

<b>ASIA PACIFIC</b>	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	CHINA: 400-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA 1800 801435 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
	<b>LATIN AMERICA</b>	BRAZIL 08000562613 (Toll Free) <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customerService@panduit.com">MEX-customerService@panduit.com</a>	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	EMEA: +44 208 6017219 <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

NK6X88MIG
NK6X88MBL
NK6X88MGR
NK6X88MBU
NK6X88MBU
NK6X88MWH
NK688MGR-Q
NK688MBU-Q
NK688MEI-Q
NK688MBL-Q
NK688MOR-Q
NK688MIG-Q
NK688MIW-Q
NK688MWH-Q
NK688MYL-Q
NK688MAW
NK688MIW
NK688MBL
NK688MGR
NK688MIG
NK688MYL
NK688MBU
NK688MEI
NK688MOR
NK688MRD
NK688MWH
NK688MVL
NKP5E88MWH
NKP5E88MBU-Q
NKP5E88MYL
NKP5E88MBU
NKP5E88MEI
NKP5E88MGR
NKP5E88MOR
NKP5E88MBL
NKP5E88MBL-Q
NKP5E88MIW-Q
NKP5E88MOR-Q
NKP5E88MWH-Q
NKP5E88MIG
NKP5E88MIW
NKP5E88MRD