

Customer Product/Process Change Notification

PCN # 104277

Date: 06/14/23

Issued

			Issued By:	Cheryll Santiago	
			•	Cheryll Santiago	
Change affects whole product family?		No			
Part #'s affected (See attached if entire	product family is affected)				
597-3327-502F/-507F, 597-3907-502F/-507F, 597-2603-502F/507F, 597-2323-502F/507F, 597-2903-502F/507F, 597-3322-502F/507F, 597-3602-502F/507F, 597-3902-502F/507F					
Description of Change:					
New LED Die material is higher bright	ness				
Decree for Observe					
Reason for Change:					
Old LED Die is EOL					
Properties of Old vs. Changed Product:					
See Comparison sheets					
Disposition of Old Product:					
Deplete existing Stock on hand.					
, 5					

Expected Implementation Date:

Immediate Not Customer Feedback Expected by: Applicable

Director of Quality:

Last Time Buy Date:

Not Applicable See inventory tab

Additional Comments: (Include Potential Risks if Appropriate)				
Replacement 0402 SMT LED is slightly different package shape (597-3327-502F/-507F and 597-3907-502F/-507F).				
Supporting Qualification Data.				
Supporting Qualification Data:				
When Available upon request only.				
Approved By:				
(Minimum of three approvals are required.)				
Vice President of Operations:				
Vice President of Sales OED/Signals:				
Director of Customer Service:				
Vice President of Marketing:				