

Not to be disclosed to any party other than the intended recipient

## **Engineering Change Notice**

ECNS17-001-3 April 20, 2017

#### 1. Object

Change Marking of Signal Relay

#### 2. Product

All signal relay (EA2 / EB2 / EC2 / EE2 / ED2 / EF2 / UA2 / UB2 / UC2 / UD2 series)

### 3. Contents of Change

Series	Current	New
EA2/EB2 (Example:EA2-5NU)	EA2-5NU  NEC  JAPAN  1D1701F	EA2-5NU JAPAN NEXEM1D1727F
EC2/EE2/ED2/EF2 (Example:EC2-5NU)	EC2-5NU NEC SASS  JAPAN 1C1701F	EC2-5NU JAPAN PASP NEXEM 1C1727F
UA2/UB2 (Example:UA2-5NU)	1A1701F UA2-5NU NEC JAPAN	1A1727F UA2-5NU NEXEM JAPAN
UC2/UD2 (Example:UC2-5NU)	NEC JAPAN UC2-5NU 1A1701F	1A1727F ■ UC2-5NU NEXEM JAPAN

Note) This is just only the company logo change.

There isn't change the product specification and the packing specification. File number of safety standard and rating is not changed. (UL, CSA, TUV)

# 4.Reasons of Change

Business unit of relay splits off from NEC TOKIN and will be a stand-alone company.

## 5. Application

This change will be applied from the production of July, 2017 (Date code from 1727).

Masao Saito
Sales Promotion & Marketing Department Manager
and Field Application Engineering Group Manager
EM Devices Corporation