

Global Change Notification (GCN)

Product Family	1.0 FFC CONN NON ZIF SMT (R/A)	10685928	
		GCN Number	
Series	52852	May 14, 2015	
		Date Issued	
Reason For Change	Outsourcing Component Or Subcomponent		
Change Description	The purpose of this letter is to add Linear Precision Manufacturing Pte. Ltd. as additional manufacturing location for 52852 housing series. The reason is to make sure there is assurance of supply for 52852 parts. This changes only apply to Molex Malaysia plant. The material is produce per Molex specification. There is no change in design and process for Molex Malaysia, therefore no change in the Molex assembly part number will occur either. Sample can be provided upon request. First article inspection will be done. The implementation will be running change.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	mail message.	
Reason For Short Notice Exception	New Capacity		
Assessment Of Change (How Product Will Be Qualified & Validated)	Based on first Article Inspection		
Internal Molex Qualification Date (Planned Date Information Available)	May 20, 2015		
Sample Availability Date (Changed Part)	May 21, 2015		
Date of Implementation	June 27, 2015		
Method of Identifying Change	Based on label information		
Recommended Replacement Parts	Not applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com