

PCN# : P29CA Issue Date : Oct. 23, 2012

DESIGN/PROCESS CHANGE NOTIFICATION

This is to inform you that a change is being made to the products listed below.

Unless otherwise indicated in the details of this notification, the identified change will have no impact on product quality, reliability, electrical, visual or mechanical performance and affected products will remain fully compliant to all published specifications. Products incorporating this change may be shipped interchangeably with existing unchanged products.

This change is planned to take effect in 90 calendar days from the date of this notification. Please work with your local Fairchild Sales Representative to manage your inventory of unchanged product if your evaluation of this change will require more than 90 calendar days.

Please contact your local Customer Quality Engineer within 30 days of receipt of this notification if you require any additional data or samples. Alternatively, you may send an email request for data, samples or other information to PCNSupport@fairchildsemi.com.

Implementation of change:

Expected First Shipment Date for Changed Product : Jan. 21, 2013

Expected First Date Code of Changed Product :1301

Description of Change (From) : DO35&DO41 bulk products label change: 1. Soabar label

2. Label dimension:82 x 40mm

FAI	RCHILD		
SEMI		P.O.No.	
TYPE	1N4148	MARK	
REV	A4	PART No	
PKG		EC No.	
QTY	1,000	M.O.No.	F11360086Z
Q.C.		DATE	A1136TC

Description of Change (To) : DO35&DO41 bulk products label change:

- 1. Bar code label
- 2. Label dimension:96 x 40mm
- 3. Will be using barcode symbology code 39

LOT: F12360006N FSID: 1N4148 D/C1: A1236TC QTY1: D/C2: QTY2:	Green Component RoHS COMPLIANT 2nd Level Interconnect 1. Category G3 2. Maximum safe temperature N/A deg C 3. MSL N/A
BOXTNR(3.1)	FAIRCHILD SEMICONDUCTOR

Reason for Change: Follow FSC corporate barcode label format.



Affected Product(s):

1N3595	1N4148	1N4149
1N4447	1N4448	1N4454
1N456A	1N457	1N457A
1N458A	1N459	1N459A
1N4728A	1N4729A	1N4730A
1N4731A	1N4732A	1N4733A
1N4734A	1N4735A	1N4736A
1N4737A	1N4738A	1N4739A
1N4740A	1N4741A	1N4742A
1N4743A	1N4744A	1N4745A
1N4746A	1N4747A	1N4748A
1N4749A	1N4750A	1N4751A
1N4752A	1N4753A	1N4754A
1N4755A	1N4756A	1N4757A
1N4758A	1N483B	1N485B
1N486B	1N5221B	1N5222B
1N5223B	1N5224B	1N5225B
1N5226B	1N5227B	1N5228B
1N5229B	1N5230B	1N5231B
1N5231C	1N5232B	1N5233B
1N5234B	1N5234C	1N5235B
1N5236B	1N5237B	1N5238B
1N5239B	1N5240B	1N5241B
1N5242B	1N5243B	1N5244B
1N5245B	1N5246B	1N5247B
1N5248B	1N5250B	1N5251B
1N5252B	1N5253B	1N5254B
1N5255B	1N5256B	1N5257B
1N5259B	1N5261B	1N5262B
1N5263B	1N5282	1N914
1N914B	1N916	1N916A
1N916B	BAV21	BAW62
BAW76	BAX16	BAY73
BZX79C10	BZX79C11	BZX79C12
BZX79C15	BZX79C20	BZX79C24
BZX79C2V4	BZX79C2V7	BZX79C33
BZX79C39	BZX79C3V0	BZX79C3V3
BZX79C3V6	BZX79C3V9	BZX79C47
BZX79C4V3	BZX79C4V7	BZX79C51
BZX79C5V1	BZX79C5V6	BZX79C6V2



Affected Product(s):

BZX79C6V8	BZX79C8V2	BZX79C9V1	
BZX85C10	BZX85C11	BZX85C12	
BZX85C13	BZX85C15	BZX85C16	
BZX85C18	BZX85C20	BZX85C22	
BZX85C24	BZX85C27	BZX85C30	
BZX85C33	BZX85C36	BZX85C3V3	
BZX85C3V6	BZX85C3V9	BZX85C47	
BZX85C4V3	BZX85C4V7	BZX85C51	
BZX85C5V1	BZX85C5V6	BZX85C6V2	
BZX85C6V8	BZX85C7V5	BZX85C8V2	
BZX85C9V1	FDH300A	FDH333	
FDH3595	FDH400	FDH444	
FJH1100	FJH1101		