



Expertise Applied | Answers Delivered

Littelfuse, Inc.
8755 West Higgins Road, Suite 500
Chicago, IL 60631 USA
(773) 628-1000

February 27, 2018

RE: Littelfuse HWB60AL Supply Change

Dear Valued Customer,

To better serve our customers by increasing responsiveness and flexibility, by the end of Q22018 we will change our manufacturing locations for plastic components associated with the HWB60AL, from an outside injection molding supplier to a Littelfuse injection molding facility.

The affected Littelfuse finished good part numbers are:

PDM71001ZXM	PDM71004ZXM
PDM71001ZXM-ICA	PDM71006ZXM
PDM71001ZXM-PCA	PDM71007ZXM
PDM71002ZXM	PDM71008ZXM
PDM71002ZXM-ICA	PDM71009ZXM
PDM71002ZXM-PCA	PDM7100CVR-ICA
PDM71003ZXM	

New quality and PPAP documentation will be prepared upon completion of the transfer and available upon request.

Please let myself or your Littelfuse sales contact know if you have any questions or concerns.

Regards,

Jeremy Glessner

Jeremy Glessner
Product Management
Automotive Business Unit, Commercial Vehicle Products
Littelfuse, Inc.
jglessner@littelfuse.com