

Mechanical handheld tachometer

HTM-100M



Application:

For contact measurement of rotation speed and surface velocity.

Version:

- Large analogue display
- Button-actuated pointer lock for saving the last measurement
- Battery-free operation
- Plastic housing

Delivery:

Tachometer, measuring wheel (0.1 m), measuring tip, hollow measuring tip, extension, operating instructions



Art. no.	39330 100
Max. rotation speed of measuring range (contact)	10 rpm
Error limit (%)	0.5 %

EAN-Code

4251420200006