

Global Change Notification (GCN)

Product Family KK396 10734164

GCN Number

Series 41771, 41772, 46995 December 17, 2015

Date Issued

Reason For Change

New, Modified, Or Replacement Tooling

Change Description

This letter is to inform you that a replacement mold is being built for the housings used on 41771, 41772, and 46995 series. The new mold will run at the Maumelle, Arkansas facility instead of the Lincoln, Nebraska facility.





Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	Product will be qualified	
Internal Molex Qualification Date (Planned Date Information Available)	April 15, 2016	
Sample Availability Date (Changed Part)	April 15, 2016	
Date of Implementation	April 15, 2016	
Method of Identifying Change	Cavity ID	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com