

Test unit for sensors analog & digital

- Output via display (V or mA) or LED (PNP/NPN)
- Teach-in of sensors with integrated Teach- button
- Connection for plug in power supply (available as accessory)

Test- and configuration device for analog and digital PNP/NPN sensors with 18 VDC supply voltage

order reference

11084376 Test unit for sensors analog&digital

Test unit for sensors digital

- LED (red/green) for digital PNP/NPN signals
- Teach-in of sensors with integrated Teach- button
- Connection for plug in power supply (available as accessory)

Test- and configuration device for digital PNP/NPN sensors with 18 VDC supply voltage

order reference

11084377 Test unit for sensors digital


Power supply for sensor test unit

- Input 100-230 VAC
- Output 24 V/0,3 A
- Euro 2 pin plug connector

Protects the batteries of the sensor tester analog & digital for extended lifetime

order reference


11087165 Test unit for sensors

PNP to NPN Converter M8

- PNP/NPN Converter
- For frequencies up to max. 5 kHz
- For connector M8 - 3 pins

order reference

10161959 Converter PNP/NPN - M8 x 1

PNP to NPN Converter M12

- PNP/NPN Converter
- For frequencies up to max. 5 kHz
- For connector M12 - 3 pins

order reference

10161958 Converter PNP/NPN - M12 x 1