



Product Change Notification

Current Date: 03-Nov-2017

TE Connectivity

Product Change Notification: P-17-014989

PCN Date: 29-OCT-17

Customer: DISTRIBUTOR NA (66666661)

Location: NO CITY PROVIDED

Agreement: 120513180001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Inverted modular jack

Description of Changes

The assembly line of following Part Numbers will be transferred from out side vendor to TE AMP ShangHai plant.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of assembly line of modular jack. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the related products. The new manufacturing location operates under a certified quality management system. A TE-internal release test based on the relevant part specifications will be executed before delivery. If you require a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 08-DEC-2017 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-406507-1 | NO | | | | | | |
| 1-406507-5 | NO | | | | | | |
| 1-406507-7 | NO | | | | | | |
| 1-406525-2 | NO | | | | | | |
| 1-406541-4 | NO | | | | | | |
| 1-406541-7 | NO | | | | | | |
| 1-406541-8 | NO | | | | | | |
| 1-406541-9 | NO | | | | | | |
| 1-5406533-8 | NO | | | | | | |
| 1-5406552-1 | NO | | | | | | |
| 1-5406552-3 | NO | | | | | | |
| 1-5406552-4 | NO | | | | | | |
| 1-5406552-5 | NO | | | | | | |
| 1-5406552-6 | NO | | | | | | |
| 1-5406552-7 | NO | | | | | | |
| 1-5406552-9 | NO | | | | | | |
| 1-6116353-3 | NO | | | | | | |
| 1116075-2 | NO | | | | | | |
| 1116132-1 | NO | | | | | | |
| 1116132-6 | NO | | | | | | |
| 1116132-8 | NO | | | | | | |
| 1116173-1 | NO | | | | | | |
| 1116173-4 | NO | | | | | | |
| 1116173-5 | NO | | | | | | |
| 1116353-1 | NO | | | | | | |
| 1116353-6 | NO | | | | | | |
| 1116522-1 | NO | | | | | | |
| 1364173-5 | NO | | | | | | |
| 1761791-2 | NO | | | | | | |
| 1761791-3 | NO | | | | | | |
| 1761791-4 | NO | | | | | | |
| 1761791-5 | NO | | | | | | |
| 1888298-1 | NO | | | | | | |
| 1888566-2 | NO | | | | | | |
| 1888630-1 | NO | | | | | | |
| 1932112-1 | NO | | | | | | |
| 1932389-1 | NO | | | | | | |
| 2-406507-4 | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|---------------------------------|------------------------|---------------------------------|---------------------------|
| 2-406541-1 | NO | | | | | | |
| 2-406541-2 | NO | | | | | | |
| 2-406541-3 | NO | | | | | | |
| 2-406549-2 | NO | | | | | | |
| 2-406549-4 | NO | | | "A69961-000", "AMP-2-0406549-4" | | | |
| 2-406549-7 | NO | | | | | | |
| 2-406549-8 | NO | | | "P04065-000" | | | |
| 2-406549-9 | NO | | | | | | |
| 2-6116353-4 | NO | | | | | | |
| 2-6116353-8 | NO | | | "CC1020-000", "AMP-2-6116353-8" | | | |
| 2-6116353-9 | NO | | | | | | |
| 2-6368144-1 | NO | | | | | | |
| 2007073-1 | NO | | | | | | |
| 2007073-2 | NO | | | | | | |
| 2170354-1 | NO | | | | | | |
| 2170358-1 | NO | | | | | | |
| 2170359-1 | NO | | | | | | |
| 3-406507-7 | NO | | | | | | |
| 3-406549-0 | NO | | | | | | |
| 3-406549-1 | NO | | | | | | |
| 3-406549-2 | NO | | | | | | |
| 3-406549-3 | NO | | | | | | |
| 3-406549-8 | NO | | | | | | |
| 3-6116353-1 | NO | | | | | | |
| 406507-1 | NO | | | "1119029" | | | |
| 406507-4 | NO | | | | | | |
| 406508-6 | NO | | | | | | |
| 406525-1 | NO | | | "1054579" | | | |
| 406526-1 | NO | | | | | | |
| 406533-1 | NO | | | | | | |
| 406536-7 | NO | | | | | | |
| 406541-1 | NO | | | | | | |
| 406541-4 | NO | | | | | | |
| 406549-1 | NO | | | "29-00045-01", "1950351P009" | | | |
| 406549-4 | NO | | | "F23618-000", "AMP-0-0406549-4" | | | |
| 406549-5 | NO | | | "1257120" | | | |
| 406549-8 | NO | | | "E56507-000", "AMP-0-0406549-8" | | | |
| 406552-1 | NO | | | | | | |
| 406552-4 | NO | | | | | | |
| 406552-5 | NO | | | | | | |
| 406967-3 | NO | | | | | | |
| 5406526-1 | NO | | | | | | |
| 5406528-1 | NO | | | | | | |
| 5406533-1 | NO | | | | | | |
| 5406533-5 | NO | | | | | | |
| 5406533-7 | NO | | | | | | |
| 5406534-2 | NO | | | | | | |
| 5406536-8 | NO | | | | | | |
| 5406544-1 | NO | | | | | | |
| 5406544-2 | NO | | | | | | |
| 5406552-2 | NO | | | | | | |
| 5406552-4 | NO | | | | | | |
| 5406552-5 | NO | | | | | | |
| 5406552-7 | NO | | | | | | |
| 5406552-8 | NO | | | | | | |
| 5406552-9 | NO | | | | | | |
| 5406554-2 | NO | | | | | | |
| 5406554-4 | NO | | | | | | |
| 5406554-5 | NO | | | | | | |
| 5406554-7 | NO | | | | | | |
| 5406554-8 | NO | | | | | | |
| 5406554-9 | NO | | | | | | |
| 5406556-1 | NO | | | | | | |
| 5406556-4 | NO | | | | | | |
| 5406967-4 | NO | | | | | | |
| 5406967-5 | NO | | | | | | |
| 5406967-8 | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|---------------------------------|------------------------|---------------------------------|---------------------------|
| 6116075-1 | NO | | | | | | |
| 6116075-4 | NO | | | "CF0103-000", "AMP-0-6116075-4" | | | |
| 6116075-5 | NO | | | | | | |
| 6116075-6 | NO | | | | | | |
| 6116075-7 | NO | | | | | | |
| 6116115-4 | NO | | | | | | |
| 6116132-1 | NO | | | | | | |
| 6116132-5 | NO | | | | | | |
| 6116132-8 | NO | | | | | | |
| 6116173-1 | NO | | | "CA6961-000", "PER-0-6116173-1" | | | |
| 6116173-4 | NO | | | | | | |
| 6116173-5 | NO | | | | | | |
| 6116301-1 | NO | | | | | | |
| 6116353-2 | NO | | | | | | |
| 6116353-4 | NO | | | | | | |
| 6116353-5 | NO | | | | | | |
| 6116353-8 | NO | | | | | | |
| 6116522-1 | NO | | | | | | |
| 6116522-2 | NO | | | | | | |
| 6116615-4 | NO | | | | | | |
| 6116615-5 | NO | | | | | | |
| 6116615-6 | NO | | | | | | |
| 6364139-5 | NO | | | | | | |
| 6364173-5 | NO | | | | | | |
| 6364288-4 | NO | | | | | | |
| 6368214-8 | NO | | | | | | |
| 6368419-1 | NO | | | | | | |
| 6368459-1 | NO | | | | | | |
| 6368460-4 | NO | | | | | | |