



工程變更客戶通知單

Engineering Change Customer Notification

ECR/ECN 單號： ECR/ECN Number:	EO000231
日期： Date:	2024/06/13
變更者/郵箱： Author/Mail	Paul Liu
客戶端工程變更需求確認：(signature) EC request confirmation by customer	請於 10 工作日內簽回，若超過 10 日未簽回將視為同意此變更 Please sign back within 10 working days, if you do not sign back within 10 working days, you will be deemed to agree to this change.
客戶端工程變更完成確認：(signature) EC completion confirmation by customer	請於 10 工作日內簽回，若超過 10 日未簽回將視為已確認 Please sign back within 10 working days, if you do not sign back within 10 working days, it will be deemed as confirmed.

1. 影響產品 Affected Products

產品類別 Product Category	零件編號 Part Number
	AGGBLA.125.A ASGGB184.A ASGGB254.A DSGP.1575.15.4.A.02 DSGP.1575.18.2.A.02 SGPDF254.A SGGP.12.4.A.02 PCS.55.A PCS.66.A PCS.86.A PA.500.A PCS.06.M PA.760.A PCS.68.A PA.740.A NCP.5820 NCS.5820 PA.26A

	PCS.25.A SWDP.2458.15.4.A.02 WLA.10 WLA.01 SWLP.2450.10.4.A.02 SWLP.2450.12.4.B.02 ILA.08 ILA.09 ILA.02 CA.69 UWA.01 UWC.40 UWC.01 CA.51
--	---

2. 變更訊息 Information of change

變更類型 Type of Change	<input type="checkbox"/> 工程設計變更 Engineering Design Change		<input type="checkbox"/> 生產製程變更 Production Process improvement	
	<input checked="" type="checkbox"/> 其他: Packaging change			
變更原因 Reason for change	Internal MSL definition of embedded product redefine.			
變更說明 Description of Change	Implement all SMD product has MSL 3 caution label and moisture sensitive label on the vacuum bag.			
變更影響 Impact of change	<input type="checkbox"/> 外觀 Appearance		<input type="checkbox"/> 功能 Function	
	<input type="checkbox"/> 品質 Quality		<input type="checkbox"/> 規格 Specification	
		<input type="checkbox"/> 可靠度 Reliability		<input type="checkbox"/> 法規 Regulations
		<input checked="" type="checkbox"/> 包裝 Package:		<input type="checkbox"/> 其他 Others:
上述影響描述: Describe if above applies: Yes		Packaging change.		
預估轉換日期 Forecast Estimated Transition Date	Last buy (old product)		running change	
	New buy (new product)		running change	

3. 計劃表

N/A

4. 變更圖例

Illustration of Change

變更前/Before

No MSL 3 caution label and moisture sensitive label.



- 1 PCS / Vacuum bag
- 2 PCS / 3g Desiccant
- 1 PCS / Humidity test paper
- SPQ Label

變更後/After

Add MSL 3 caution label and moisture sensitive label on the vacuum bag.



- 1 PCS / Vacuum bag
- 2 PCS / 3g Desiccant
- 1 PCS / Humidity test paper
- SPQ Label