



Product Change Notification

Date Issued :	December 22, 2022	PCN Number :	513058
Reason for Change :	Change to Product		
Description of Change :	Changed position of LISTED homologation of the marking on the cable.		
Reason for Short Notice :	Corrective Actions		
Assessment of Change :	First Article Inspection		
Planned Implementation Date :	December 23, 2022		
Sample Availability Date:	December 13, 2022		
Internal Molex Qualification Date :	December 13, 2022		
Last date to request Samples by Customer :	December 23, 2022		
Traceability Code Markings / Date :	Special marking on the product or packaging		

Before Picture

Overview

- This document is to inform you that Flamar is updating the marking of some product that have LISTED homologation.
- The modify will be the position of marks ITC and PLTC and the file number associated the LISTED homologation type.
- The purpose of this change is to align the marking with the UL reference request.
- The change will NOT impact fit, form and function of the product.
- See attached the impacted parts list.
- The pictures below represents an example to the change.

After Picture

- Example of the modification you will find on the cable

BEFORE CHANGE

(UL) 22 AWG/3 PLTC 105C E470965 OR ITC SUN RES OIL RES II (-40C) 105C OR CSA

LL107556 AWM I/II A/B 90C 300V FT4

AFTER CHANGE

(UL) 22 AWG/3 ITC 105C E474950 OR PLTC SUN RES OIL RES II (-40C) 105C OR CSA

LL107556 AWM I/II A/B 90C 300V FT4

RELEASED

You may address inquires regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:513058
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 513058** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com