



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019874

PCN Date: 20-OCT-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
069359-000	NO			9-1190521-6, 201M128-19C			
140070-000	NO		RAY140070-000	6-1191015-3, 203M016-19B10			
152201-000	NO			1191100-9, TXR54AB00-1812BI			
167451-000	NO		RAY167451-000	1-1191219-9, STXR40AB00-1210AI			
224077-000	NO			8-1191650-5, TXR40AB90-1005AI			
252406-000	NO			3-1199929-9, TXS104AB00-1005AI			
256493-000	NO			1191877-3, STXR41AB00-1210AI			
278451-000	NO			6-1192061-5, TXR54AB00-2214AI			
301227-000	NO			1-1192282-2, TXR40BW00-0804AI			
334781-000	NO			9-1192528-0, 202M216-19B			
347583-000	NO			7-1192615-6, TXR40BW00-2014AI			
355597-000	NO		RAY355597-000	5-1192669-9, TXR40BW00-1812AI			
421397-000	NO		RAY421397-000	3-1193174-3, TXR40AB00-2014AI			
440177-000	NO			1193309-6, TXR41AB00-2212AI			
443143-000	NO			1193331-4, 204M116-19B04-40			
447297-000	NO			3-1193361-8, TXR76AB00-1605AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
481087-000	NO			1-1193601-8, TXR76AB00-1204AI			
495693-000	NO			4-1193707-2, TXR41AB00-1410BI			
535325-000	NO		RAY535325-000	2-1194203-3, TXR41AB00-1608AI			
540553-000	NO			2-1194240-1, TXR40AC00-2414AI			
554173-000	NO		RAY554173-000	5-1194375-5, TXR40AB00-1406AI			
572809-000	NO			8-1194547-6, TXR40AB00-2216AI			
621387-000	NO			9-1194910-8, TXR76AB00-1405AI			
671613-000	NO			9-1195284-0, TXR40AC00-1210AI			
697581-000	NO		RAY697581-000	1195475-3, TXR41AB00-1607AI			
778005-000	NO		RAY778005-000	9-1196055-5, TXR40AB00-1205AI			
808656-000	NO			3-1196279-2, 201M122-19C			
812043-000	NO		RAY812043-000, RAYTXR40AB00-1810BI	9-1196316-4, TXR40AB00-1810BI			
826827-000	NO			3-1196458-7, TXR40SJ00-1007AI			
864163-000	NO			3-1196730-8, TXR40BW00-1408AI			
913885-000	NO		RAY913885-000	8-1197095-4, TXR40AB00-1812AI			
931957-000	NO			5-1197223-3, TXR40AB00-2414AI			
982603-000	NO			1-1197592-5, 204M010-19B04-40			
AAF2661-00	NO			TXR40AB00-1408AIJ			
C73862-000	NO		RAYC73862-000	6-1200810-6, TXR40AU00-1006AI			
CA7140-000	NO			5-1899129-3, TXR40BW00-2216AI			
CF0470-000	NO			5-1899165-3, STXR40BW00-0805AI			
CF0573-000	NO		RAYCF0573-000	1-1899174-4, STXR40BW00-1210AI			
CF7703-000	NO			TXR40AB00-1208AIJ			
CV5408-000	NO			TXR40AZ00-1814BI			
CV5416-000	NO			TXR40AZ00-2218BI			
E24641-000	NO			4-1200810-2, TXR76AU00-1208AI			
EG2466-000	NO			BND18AB00-2216W			
EJ0471-000	NO			TXR40SJ00-2424AI			
EK2357-000	NO			228M714-19U			



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019874

PCN Date: 20-OCT-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
069359-000	NO			9-1190521-6, 201M128-19C			
140070-000	NO		RAY140070-000	6-1191015-3, 203M016-19B10			
152201-000	NO			1191100-9, TXR54AB00-1812BI			
167451-000	NO		RAY167451-000	1-1191219-9, STXR40AB00-1210AI			
224077-000	NO			8-1191650-5, TXR40AB90-1005AI			
252406-000	NO			3-1199929-9, TXS104AB00-1005AI			
256493-000	NO			1191877-3, STXR41AB00-1210AI			
278451-000	NO			6-1192061-5, TXR54AB00-2214AI			
301227-000	NO			1-1192282-2, TXR40BW00-0804AI			
334781-000	NO			9-1192528-0, 202M216-19B			
347583-000	NO			7-1192615-6, TXR40BW00-2014AI			
355597-000	NO		RAY355597-000	5-1192669-9, TXR40BW00-1812AI			
421397-000	NO		RAY421397-000	3-1193174-3, TXR40AB00-2014AI			
440177-000	NO			1193309-6, TXR41AB00-2212AI			
443143-000	NO			1193331-4, 204M116-19B04-40			
447297-000	NO			3-1193361-8, TXR76AB00-1605AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
481087-000	NO			1-1193601-8, TXR76AB00-1204AI			
495693-000	NO			4-1193707-2, TXR41AB00-1410BI			
535325-000	NO		RAY535325-000	2-1194203-3, TXR41AB00-1608AI			
540553-000	NO			2-1194240-1, TXR40AC00-2414AI			
554173-000	NO		RAY554173-000	5-1194375-5, TXR40AB00-1406AI			
572809-000	NO			8-1194547-6, TXR40AB00-2216AI			
621387-000	NO			9-1194910-8, TXR76AB00-1405AI			
671613-000	NO			9-1195284-0, TXR40AC00-1210AI			
697581-000	NO		RAY697581-000	1195475-3, TXR41AB00-1607AI			
778005-000	NO		RAY778005-000	9-1196055-5, TXR40AB00-1205AI			
808656-000	NO			3-1196279-2, 201M122-19C			
812043-000	NO		RAY812043-000, RAYTXR40AB00-1810BI	9-1196316-4, TXR40AB00-1810BI			
826827-000	NO			3-1196458-7, TXR40SJ00-1007AI			
864163-000	NO			3-1196730-8, TXR40BW00-1408AI			
913885-000	NO		RAY913885-000	8-1197095-4, TXR40AB00-1812AI			
931957-000	NO			5-1197223-3, TXR40AB00-2414AI			
982603-000	NO			1-1197592-5, 204M010-19B04-40			
AAF2661-00	NO			TXR40AB00-1408AIJ			
C73862-000	NO		RAYC73862-000	6-1200810-6, TXR40AU00-1006AI			
CA7140-000	NO			5-1899129-3, TXR40BW00-2216AI			
CF0470-000	NO			5-1899165-3, STXR40BW00-0805AI			
CF0573-000	NO		RAYCF0573-000	1-1899174-4, STXR40BW00-1210AI			
CF7703-000	NO			TXR40AB00-1208AIJ			
CV5408-000	NO			TXR40AZ00-1814BI			
CV5416-000	NO			TXR40AZ00-2218BI			
E24641-000	NO			4-1200810-2, TXR76AU00-1208AI			
EG2466-000	NO			BND18AB00-2216W			
EJ0471-000	NO			TXR40SJ00-2424AI			
EK2357-000	NO			228M714-19U			