


Product Change Notification (PCN)

PCN Number	501881	Date Issued	March 17, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Special Request		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	December 01, 2016		
Sample Availability Date (Changed Part)	December 01, 2016		
Planned Implementation Date	November 01, 2017		
Method of Identifying Change	Lot information on label		

RELEASED

Before Change



After Change

Overview

- Plating process will be changed with the project transfer from LNK to CD. The new plating will have gold flash in the initial contact area and 50u gold in the contact resting area vs. the old process with nickel plating in initial contact area and 50u gold in the contact resting area. The only impact is the slight visual difference to the terminal plating, otherwise fit and function are not affected.
- Product Impact
 - no impact to fit and function
- Part Number Impact
 - see attached impacted parts list
- PPAP and samples available upon request




© 2017 Molex - All rights reserved. Unauthorized reproduction is prohibited.



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501881**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com