

## PRODUCT CHANGE NOTICE

**PCN Number** : 234

**Product Category** : Pin Headers.

**Issue Date** : 17 - AUG - 2021

**Effective Date** : 17 - AUG - 2021

**LTB Date** : N/A

**LTD Date** : N/A

**Reason For Change** : Change in Insulator material Nylon 66 (UL94V-2) to Nylon 66 (UL94V-0) type due to shortage of material and upgrade quality.

**Change to Form Fit Function** : No change in form fit & function.

**Part Effected** : Below are the parts which are affected with this change.

FARNELL SKU	NEWARK SKU	PART NUMBER	FARNELL SKU	NEWARK SKU	PART NUMBER
1578520	02N4692	MC34925	1578495	02N4685	MC34665
1578519	02N4691	MC34923	1578496	02N4686	MC34667
1578521	02N4693	MC34927	1578498	02N4688	MC34777
1578490	02N4681	MC34657	1578500	02N4690	MC34779
1578491	02N4682	MC34659	1578501	02N4694	MC34311
1578493	02N4683	MC34661	1578502	02N4695	MC34669
1578494	02N4684	MC34663	-	-	-

**Important Notice** : This PCN and its contents (the "Information") belong to the members of the AVNET group of companies (the "Group") or are licensed to it. No licence is granted for the use of it other than for information purposes in connection with the products to which it relates. No licence of any intellectual property rights is granted. The Information is subject to change without notice and replaces all data sheets previously supplied. The Information supplied is believed to be accurate but the Group assumes no responsibility for its accuracy or completeness, any error in or omission from it or for any use made of it. Users of this data sheet should check for themselves the Information and the suitability of the products for their purpose and not make any assumptions based on information included or omitted. Liability for loss or damage resulting from any reliance on the Information or use of it (including liability resulting from negligence or where the Group was aware of the possibility of such loss or damage arising) is excluded. This will not operate to limit or restrict the Group's liability for death or personal injury resulting from its negligence. Multicomp Pro is the registered trademark of Premier Farnell Limited 2019.