



The DNA of tech.™

Change of epoxy coating - Industrial leaded MLCC (A series)

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Mark Walsh
One Greenwich Place
-
Shelton United States 06484
Phone: 978-474-4254
Fax:
-

Europe

Dr. Florian Weyland
Dr.-Felix-Zandman-Platz 1
-
Selb Germany 95100
Phone: +49-9287-71-2787
Fax:
-

Asia

Boonhooi Tan
37A Tampines St. 92 #07-00
-
Singapore Singapore 528886
Phone: +65-6780-7759
Fax:
-

Description of Change: We will change the epoxy coating of the industrial leaded MLCC A series. Parts with new epoxy coating will be sent starting April 2025. The color of the epoxy will change from yellow to blue. There will be no change in form/fit/function.

Reason for Change: Obsolescence of the current epoxy from April 2025 on.

Expected Influence on Quality/Reliability/Performance: Quality/Reliability/Performance will stay the same - no influence

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay BCcomponents

Time Schedule:

Start Shipment Date: Mon Apr 28, 2025

Sample Availability: on request

Product Identification: By series name (A series)

Qualification Data: on request

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Wed Feb 21, 2024 or as specified by contract.

Issued By: Florian Weyland, florian.weyland@vishay.com



Product Change Notification



Product Group: CC/Mon Jan 22, 2024/PCN-CC-00002-2024-REV-0

The DNA of tech.™

| | | | | |
|------------------|-----------------|--------------------|--------------------|-----------------|
| A100J15C0GF5TAA | A100J15C0GF5UAA | A100J15C0GH5TAA | A100J15C0GH5UAA | A100K15C0GF5TAA |
| A100K15C0GF5UAA | A100K15C0GH5TAA | A100K15C0GH5UAA | A101J15C0GF5TAA | A101J15C0GF5UAA |
| A101J15C0GH5TAA | A101J15C0GH5UAA | A101J15C0GK5TAA | A101J15C0GK5UAA | A101J15C0GL5TAA |
| A101J15C0GL5UAA | A101K15C0GF5TAA | A101K15C0GF5UAA | A101K15C0GH5TAA | A101K15C0GH5UAA |
| A101K15C0GK5TAA | A101K15C0GK5UAA | A101K15C0GL5TAA | A101K15C0GL5UAA | A101K15X7RF5TAA |
| A101K15X7RF5UAA | A101K15X7RH5TAA | A101K15X7RH5UAA | A101K15X7RK5TAA | A101K15X7RK5UAA |
| A101K15X7RL5TAA | A101K15X7RL5UAA | A101M15X7RF5TAA | A101M15X7RF5UAA | A101M15X7RH5TAA |
| A101M15X7RH5UAA | A101M15X7RK5TAA | A101M15X7RK5UAA | A101M15X7RL5TAA | A101M15X7RL5UAA |
| A102J15C0GF5TAA | A102J15C0GF5UAA | A102J15C0GF5UAA-XA | A102J20C0GH5TAA | A102J20C0GH5UAA |
| A102J20C0GK5TAA | A102J20C0GK5UAA | A102J20C0GL5TAA | A102J20C0GL5UAA | A102K15C0GF5TAA |
| A102K15C0GF5UAA | A102K15X7RF5TAA | A102K15X7RF5UAA | A102K15X7RF5UAA-XA | A102K15X7RH5TAA |
| A102K15X7RH5TAAW | A102K15X7RH5UAA | A102K15X7RK5TAA | A102K15X7RK5UAA | A102K15X7RL5TAA |
| A102K15X7RL5UAA | A102K20C0GH5TAA | A102K20C0GH5UAA | A102K20C0GK5TAA | A102K20C0GK5UAA |
| A102K20C0GL5TAA | A102K20C0GL5UAA | A102M15X7RF5TAA | A102M15X7RF5UAA | A102M15X7RH5TAA |
| A102M15X7RH5UAA | A102M15X7RK5TAA | A102M15X7RK5UAA | A102M15X7RL5TAA | A102M15X7RL5UAA |
| A103K15X7RF5TAA | A103K15X7RF5UAA | A103K15X7RF5UAA-XA | A103K15X7RH5TAA | A103K15X7RH5UAA |
| A103K15X7RK5TAA | A103K15X7RK5UAA | A103K20X7RL5TAA | A103K20X7RL5UAA | A103M15X7RF5TAA |
| A103M15X7RF5UAA | A103M15X7RH5TAA | A103M15X7RH5UAA | A103M15X7RK5TAA | A103M15X7RK5UAA |
| A103M20X7RL5TAA | A103M20X7RL5UAA | A104K15X7RF5TAA | A104K15X7RF5UAA | A104K20X7RH5TAA |
| A104K20X7RH5TAAW | A104K20X7RH5UAA | A104M15X7RF5TAA | A104M15X7RF5UAA | A104M20X7RH5TAA |
| A104M20X7RH5UAA | A104Z15Y5VF5UAA | A105K20X7RF5TAA | A105K20X7RF5UAA | A105Z20Y5VF5UAA |
| A120J15C0GF5TAA | A120J15C0GF5UAA | A120J15C0GH5TAA | A120J15C0GH5UAA | A120K15C0GF5TAA |
| A120K15C0GF5UAA | A120K15C0GH5TAA | A120K15C0GH5UAA | A121J15C0GF5TAA | A121J15C0GF5UAA |
| A121J15C0GH5TAA | A121J15C0GH5UAA | A121J15C0GK5TAA | A121J15C0GK5UAA | A121J15C0GL5TAA |
| A121J15C0GL5UAA | A121K15C0GF5TAA | A121K15C0GF5UAA | A121K15C0GH5TAA | A121K15C0GH5UAA |
| A121K15C0GK5TAA | A121K15C0GK5UAA | A121K15C0GL5TAA | A121K15C0GL5UAA | A121K15X7RF5TAA |
| A121K15X7RF5UAA | A121K15X7RH5TAA | A121K15X7RH5UAA | A121K15X7RK5TAA | A121K15X7RK5UAA |
| A121K15X7RL5TAA | A121K15X7RL5UAA | A121M15X7RF5TAA | A121M15X7RF5UAA | A121M15X7RH5TAA |
| A121M15X7RH5UAA | A121M15X7RK5TAA | A121M15X7RK5UAA | A121M15X7RL5TAA | A121M15X7RL5UAA |
| A122J15C0GF5TAA | A122J15C0GF5UAA | A122J20C0GH5TAA | A122J20C0GH5UAA | A122J20C0GK5TAA |
| A122J20C0GK5UAA | A122K15C0GF5TAA | A122K15C0GF5UAA | A122K15X7RF5TAA | A122K15X7RF5UAA |
| A122K15X7RH5TAA | A122K15X7RH5UAA | A122K15X7RK5TAA | A122K15X7RK5UAA | A122K15X7RL5TAA |
| A122K15X7RL5UAA | A122K20C0GH5TAA | A122K20C0GH5UAA | A122K20C0GK5TAA | A122K20C0GK5UAA |
| A122M15X7RF5TAA | A122M15X7RF5UAA | A122M15X7RH5TAA | A122M15X7RH5UAA | A122M15X7RK5TAA |
| A122M15X7RK5UAA | A122M15X7RL5TAA | A122M15X7RL5UAA | A123K15X7RF5TAA | A123K15X7RF5UAA |
| A123K15X7RH5TAA | A123K15X7RH5UAA | A123K15X7RK5TAA | A123K15X7RK5UAA | A123K20X7RL5TAA |
| A123K20X7RL5UAA | A123M15X7RF5TAA | A123M15X7RF5UAA | A123M15X7RH5TAA | A123M15X7RH5UAA |
| A123M15X7RK5TAA | A123M15X7RK5UAA | A123M20X7RL5TAA | A123M20X7RL5UAA | A124K20X7RF5TAA |
| A124K20X7RF5UAA | A124M20X7RF5TAA | A124M20X7RF5UAA | A131J15C0GF5TAA | A150J15C0GF5TAA |
| A150J15C0GF5UAA | A150J15C0GH5TAA | A150J15C0GH5UAA | A150K15C0GF5TAA | A150K15C0GF5UAA |
| A150K15C0GH5TAA | A150K15C0GH5UAA | A151J15C0GF5TAA | A151J15C0GF5UAA | A151J15C0GH5TAA |
| A151J15C0GH5UAA | A151J15C0GK5TAA | A151J15C0GK5UAA | A151J15C0GL5TAA | A151J15C0GL5UAA |
| A151K15C0GF5TAA | A151K15C0GF5UAA | A151K15C0GH5TAA | A151K15C0GH5UAA | A151K15C0GK5TAA |
| A151K15C0GK5UAA | A151K15C0GL5TAA | A151K15C0GL5UAA | A151K15X7RF5TAA | A151K15X7RF5UAA |
| A151K15X7RH5TAA | A151K15X7RH5UAA | A151K15X7RK5TAA | A151K15X7RK5UAA | A151K15X7RL5TAA |
| A151K15X7RL5UAA | A151M15X7RF5TAA | A151M15X7RF5UAA | A151M15X7RH5TAA | A151M15X7RH5UAA |
| A151M15X7RK5TAA | A151M15X7RK5UAA | A151M15X7RL5TAA | A151M15X7RL5UAA | A152J15C0GF5TAA |
| A152J15C0GF5UAA | A152J20C0GH5TAA | A152J20C0GH5UAA | A152J20C0GK5TAA | A152J20C0GK5UAA |
| A152K15C0GF5TAA | A152K15C0GF5UAA | A152K15X7RF5TAA | A152K15X7RF5UAA | A152K15X7RH5TAA |
| A152K15X7RH5UAA | A152K15X7RK5TAA | A152K15X7RK5UAA | A152K15X7RL5TAA | A152K15X7RL5UAA |
| A152K20C0GH5TAA | A152K20C0GH5UAA | A152K20C0GK5TAA | A152K20C0GK5UAA | A152M15X7RF5TAA |
| A152M15X7RF5UAA | A152M15X7RH5TAA | A152M15X7RH5UAA | A152M15X7RK5TAA | A152M15X7RK5UAA |
| A152M15X7RL5TAA | A152M15X7RL5UAA | A153K15X7RF5TAA | A153K15X7RF5UAA | A153K15X7RH5TAA |
| A153K15X7RH5UAA | A153K15X7RK5TAA | A153K15X7RK5UAA | A153K20X7RL5TAA | A153K20X7RL5UAA |
| A153M15X7RF5TAA | A153M15X7RF5UAA | A153M15X7RH5TAA | A153M15X7RH5UAA | A153M15X7RK5TAA |
| A153M15X7RK5UAA | A153M20X7RL5TAA | A153M20X7RL5UAA | A154K20X7RF5TAA | A154K20X7RF5UAA |



Product Change Notification



Product Group: CC/Mon Jan 22, 2024/PCN-CC-00002-2024-REV-0

The DNA of tech.™

| | | | | |
|-----------------|-----------------|------------------|-------------------|-----------------|
| A154M20X7RF5TAA | A154M20X7RF5UAA | A180J15C0GF5TAA | A180J15C0GF5UAA | A180J15C0GH5TAA |
| A180J15C0GH5UAA | A180K15C0GF5TAA | A180K15C0GF5UAA | A180K15C0GH5TAA | A180K15C0GH5UAA |
| A181J15C0GF5TAA | A181J15C0GF5UAA | A181J15C0GH5TAA | A181J15C0GH5UAA | A181J15C0GK5TAA |
| A181J15C0GK5UAA | A181J15C0GL5TAA | A181J15C0GL5UAA | A181K15C0GF5TAA | A181K15C0GF5UAA |
| A181K15C0GH5TAA | A181K15C0GH5UAA | A181K15C0GK5TAA | A181K15C0GK5UAA | A181K15C0GL5TAA |
| A181K15C0GL5UAA | A181K15X7RF5TAA | A181K15X7RF5UAA | A181K15X7RH5TAA | A181K15X7RH5UAA |
| A181K15X7RK5TAA | A181K15X7RK5UAA | A181K15X7RL5TAA | A181K15X7RL5UAA | A181M15X7RF5TAA |
| A181M15X7RF5UAA | A181M15X7RH5TAA | A181M15X7RH5UAA | A181M15X7RK5TAA | A181M15X7RK5UAA |
| A181M15X7RL5TAA | A181M15X7RL5UAA | A182J15C0GF5TAA | A182J15C0GF5UAA | A182J20C0GH5TAA |
| A182J20C0GH5UAA | A182J20C0GK5TAA | A182J20C0GK5UAA | A182K15C0GF5TAA | A182K15C0GF5UAA |
| A182K15X7RF5TAA | A182K15X7RF5UAA | A182K15X7RH5TAA | A182K15X7RH5UAA | A182K15X7RK5TAA |
| A182K15X7RK5UAA | A182K15X7RL5TAA | A182K15X7RL5UAA | A182K20C0GH5TAA | A182K20C0GH5UAA |
| A182K20C0GK5TAA | A182K20C0GK5UAA | A182M15X7RF5TAA | A182M15X7RF5UAA | A182M15X7RH5TAA |
| A182M15X7RH5UAA | A182M15X7RK5TAA | A182M15X7RK5UAA | A182M15X7RL5TAA | A182M15X7RL5UAA |
| A183K15X7RF5TAA | A183K15X7RF5UAA | A183K15X7RH5TAA | A183K15X7RH5UAA | A183K15X7RK5TAA |
| A183K15X7RK5UAA | A183K20X7RL5TAA | A183K20X7RL5UAA | A183M15X7RF5TAA | A183M15X7RF5UAA |
| A183M15X7RH5TAA | A183M15X7RH5UAA | A183M15X7RK5TAA | A183M15X7RK5UAA | A183M20X7RL5TAA |
| A183M20X7RL5UAA | A184K20X7RF5TAA | A200J15C0GF5TAA | A220J15C0GF5TAA | A220J15C0GF5UAA |
| A220J15C0GH5TAA | A220J15C0GH5UAA | A220K15C0GF5TAA | A220K15C0GF5UAA | A220K15C0GH5TAA |
| A220K15C0GH5UAA | A221J15C0GF5TAA | A221J15C0GF5UAA | A221J15C0GH5TAA | A221J15C0GH5UAA |
| A221J15C0GK5TAA | A221J15C0GK5UAA | A221J15C0GL5TAA | A221J15C0GL5UAA | A221K15C0GF5TAA |
| A221K15C0GF5UAA | A221K15C0GH5TAA | A221K15C0GH5TAAV | A221K15C0GH5UAA | A221K15C0GK5TAA |
| A221K15C0GK5UAA | A221K15C0GL5TAA | A221K15C0GL5UAA | A221K15X7RF5TAA | A221K15X7RF5UAA |
| A221K15X7RH5TAA | A221K15X7RH5UAA | A221K15X7RK5TAA | A221K15X7RK5UAA | A221K15X7RL5TAA |
| A221K15X7RL5UAA | A221M15X7RF5TAA | A221M15X7RF5UAA | A221M15X7RH5TAA | A221M15X7RH5UAA |
| A221M15X7RK5TAA | A221M15X7RK5UAA | A221M15X7RL5TAA | A221M15X7RL5UAA | A222J15C0GF5TAA |
| A222J15C0GF5UAA | A222J20C0GH5TAA | A222J20C0GH5UAA | A222J20C0GK5TAA | A222J20C0GK5UAA |
| A222K15C0GF5TAA | A222K15C0GF5UAA | A222K15X7RF5TAA | A222K15X7RF5TAAAR | A222K15X7RF5UAA |
| A222K15X7RH5TAA | A222K15X7RH5UAA | A222K15X7RK5TAA | A222K15X7RK5UAA | A222K15X7RL5TAA |
| A222K15X7RL5UAA | A222K20C0GH5TAA | A222K20C0GH5UAA | A222K20C0GK5TAA | A222K20C0GK5UAA |
| A222K20C0GL5TAA | A222K20C0GL5UAA | A222M15X7RF5TAA | A222M15X7RF5UAA | A222M15X7RH5TAA |
| A222M15X7RH5UAA | A222M15X7RK5TAA | A222M15X7RK5UAA | A222M15X7RL5TAA | A222M15X7RL5UAA |
| A223K15X7RF5TAA | A223K15X7RF5UAA | A223K15X7RH5TAA | A223K15X7RH5UAA | A223K15X7RK5TAA |
| A223K15X7RK5UAA | A223K20X7RL5TAA | A223K20X7RL5UAA | A223M15X7RF5TAA | A223M15X7RF5UAA |
| A223M15X7RH5TAA | A223M15X7RH5UAA | A223M15X7RK5TAA | A223M15X7RK5UAA | A223M20X7RL5TAA |
| A223M20X7RL5UAA | A224K20X7RF5TAA | A224K20X7RF5UAA | A224M20X7RF5TAA | A224M20X7RF5UAA |
| A270J15C0GF5TAA | A270J15C0GF5UAA | A270J15C0GH5TAA | A270J15C0GH5UAA | A270K15C0GF5TAA |
| A270K15C0GF5UAA | A270K15C0GH5TAA | A270K15C0GH5UAA | A271J15C0GF5TAA | A271J15C0GF5UAA |
| A271J15C0GH5TAA | A271J15C0GH5UAA | A271J15C0GK5TAA | A271J15C0GK5UAA | A271J15C0GL5TAA |
| A271J15C0GL5UAA | A271K15C0GF5TAA | A271K15C0GF5UAA | A271K15C0GH5TAA | A271K15C0GH5UAA |
| A271K15C0GK5TAA | A271K15C0GK5UAA | A271K15C0GL5TAA | A271K15C0GL5UAA | A271K15X7RF5TAA |
| A271K15X7RF5UAA | A271K15X7RH5TAA | A271K15X7RH5UAA | A271K15X7RK5TAA | A271K15X7RK5UAA |
| A271K15X7RL5TAA | A271K15X7RL5UAA | A271M15X7RF5TAA | A271M15X7RF5UAA | A271M15X7RH5TAA |
| A271M15X7RH5UAA | A271M15X7RK5TAA | A271M15X7RK5UAA | A271M15X7RL5TAA | A271M15X7RL5UAA |
| A272J20C0GF5TAA | A272J20C0GF5UAA | A272J20C0GH5TAA | A272J20C0GH5UAA | A272K15X7RF5TAA |
| A272K15X7RF5UAA | A272K15X7RH5TAA | A272K15X7RH5UAA | A272K15X7RK5TAA | A272K15X7RK5UAA |
| A272K15X7RL5TAA | A272K15X7RL5UAA | A272K20C0GF5TAA | A272K20C0GF5UAA | A272K20C0GH5TAA |
| A272K20C0GH5UAA | A272M15X7RF5TAA | A272M15X7RF5UAA | A272M15X7RH5TAA | A272M15X7RH5UAA |
| A272M15X7RK5TAA | A272M15X7RK5UAA | A272M15X7RL5TAA | A272M15X7RL5UAA | A273K15X7RF5TAA |
| A273K15X7RF5UAA | A273K20X7RH5TAA | A273K20X7RH5UAA | A273K20X7RK5TAA | A273K20X7RK5UAA |
| A273K20X7RL5TAA | A273K20X7RL5UAA | A273M15X7RF5TAA | A273M15X7RF5UAA | A273M20X7RH5TAA |
| A273M20X7RH5UAA | A273M20X7RK5TAA | A273M20X7RK5UAA | A273M20X7RL5TAA | A273M20X7RL5UAA |
| A300J15C0GF5TAA | A330J15C0GF5TAA | A330J15C0GF5UAA | A330J15C0GH5TAA | A330J15C0GH5UAA |
| A330J15C0GK5TAA | A330J15C0GK5UAA | A330J15C0GL5TAA | A330J15C0GL5UAA | A330K15C0GF5TAA |
| A330K15C0GF5UAA | A330K15C0GH5TAA | A330K15C0GH5UAA | A330K15C0GK5TAA | A330K15C0GK5UAA |
| A330K15C0GL5TAA | A330K15C0GL5UAA | A331J15C0GF5TAA | A331J15C0GF5UAA | A331J15C0GH5TAA |



Product Change Notification



Product Group: CC/Mon Jan 22, 2024/PCN-CC-00002-2024-REV-0

The DNA of tech.™

| | | | | |
|-----------------|-----------------|-----------------|-----------------|-----------------|
| A331J15C0GH5UAA | A331J15C0GK5TAA | A331J15C0GK5UAA | A331J15C0GL5TAA | A331J15C0GL5UAA |
| A331K15C0GF5TAA | A331K15C0GF5UAA | A331K15C0GH5TAA | A331K15C0GH5UAA | A331K15C0GK5TAA |
| A331K15C0GK5UAA | A331K15C0GL5TAA | A331K15C0GL5UAA | A331K15X7RF5TAA | A331K15X7RF5UAA |
| A331K15X7RH5TAA | A331K15X7RH5UAA | A331K15X7RK5TAA | A331K15X7RK5UAA | A331K15X7RL5TAA |
| A331K15X7RL5UAA | A331M15X7RF5TAA | A331M15X7RF5UAA | A331M15X7RH5TAA | A331M15X7RH5UAA |
| A331M15X7RK5TAA | A331M15X7RK5UAA | A331M15X7RL5TAA | A331M15X7RL5UAA | A332J20C0GF5TAA |
| A332J20C0GF5UAA | A332J20C0GH5TAA | A332J20C0GH5UAA | A332K15X7RF5TAA | A332K15X7RF5UAA |
| A332K15X7RH5TAA | A332K15X7RH5UAA | A332K15X7RK5TAA | A332K15X7RK5UAA | A332K20C0GF5TAA |
| A332K20C0GF5UAA | A332K20C0GH5TAA | A332K20C0GH5UAA | A332K20X7RL5TAA | A332K20X7RL5UAA |
| A332M15X7RF5TAA | A332M15X7RF5UAA | A332M15X7RH5TAA | A332M15X7RH5UAA | A332M15X7RK5TAA |
| A332M15X7RK5UAA | A332M20X7RL5TAA | A332M20X7RL5UAA | A333K15X7RF5TAA | A333K15X7RF5UAA |
| A333K20X7RH5TAA | A333K20X7RH5UAA | A333K20X7RK5TAA | A333K20X7RK5UAA | A333M15X7RF5TAA |
| A333M15X7RF5UAA | A333M20X7RH5TAA | A333M20X7RH5UAA | A333M20X7RK5TAA | A333M20X7RK5UAA |
| A334K20X7RF5TAA | A334K20X7RH5TAA | A334M20X7RF5TAA | A390J15C0GF5TAA | A390J15C0GF5UAA |
| A390J15C0GH5TAA | A390J15C0GH5UAA | A390J15C0GK5TAA | A390J15C0GK5UAA | A390J15C0GL5TAA |
| A390J15C0GL5UAA | A390K15C0GF5TAA | A390K15C0GF5UAA | A390K15C0GH5TAA | A390K15C0GH5UAA |
| A390K15C0GK5TAA | A390K15C0GK5UAA | A390K15C0GL5TAA | A390K15C0GL5UAA | A391J15C0GF5TAA |
| A391J15C0GF5UAA | A391J15C0GH5TAA | A391J15C0GH5UAA | A391J15C0GK5TAA | A391J15C0GK5UAA |
| A391J15C0GL5TAA | A391J15C0GL5UAA | A391K15C0GF5TAA | A391K15C0GF5UAA | A391K15C0GH5TAA |
| A391K15C0GH5UAA | A391K15C0GK5TAA | A391K15C0GK5UAA | A391K15C0GL5TAA | A391K15C0GL5UAA |
| A391K15X7RF5TAA | A391K15X7RF5UAA | A391K15X7RH5TAA | A391K15X7RH5UAA | A391K15X7RK5TAA |
| A391K15X7RK5UAA | A391K15X7RL5TAA | A391K15X7RL5UAA | A391M15X7RF5TAA | A391M15X7RF5UAA |
| A391M15X7RH5TAA | A391M15X7RH5UAA | A391M15X7RK5TAA | A391M15X7RK5UAA | A391M15X7RL5TAA |
| A391M15X7RL5UAA | A392J20C0GF5TAA | A392J20C0GF5UAA | A392J20C0GH5TAA | A392J20C0GH5UAA |
| A392K15X7RF5TAA | A392K15X7RF5UAA | A392K15X7RH5TAA | A392K15X7RH5UAA | A392K15X7RK5TAA |
| A392K15X7RK5UAA | A392K20C0GF5TAA | A392K20C0GF5UAA | A392K20C0GH5TAA | A392K20C0GH5UAA |
| A392K20X7RL5TAA | A392K20X7RL5UAA | A392M15X7RF5TAA | A392M15X7RF5UAA | A392M15X7RH5TAA |
| A392M15X7RH5UAA | A392M15X7RK5TAA | A392M15X7RK5UAA | A392M20X7RL5TAA | A392M20X7RL5UAA |
| A393K15X7RF5TAA | A393K15X7RF5UAA | A393K20X7RH5TAA | A393K20X7RH5UAA | A393K20X7RK5TAA |
| A393K20X7RK5UAA | A393M15X7RF5TAA | A393M15X7RF5UAA | A393M20X7RH5TAA | A393M20X7RH5UAA |
| A393M20X7RK5TAA | A393M20X7RK5UAA | A470J15C0GF5TAA | A470J15C0GF5UAA | A470J15C0GH5TAA |
| A470J15C0GH5UAA | A470J15C0GK5TAA | A470J15C0GK5UAA | A470J15C0GL5TAA | A470J15C0GL5UAA |
| A470K15C0GF5TAA | A470K15C0GF5UAA | A470K15C0GH5TAA | A470K15C0GH5UAA | A470K15C0GK5TAA |
| A470K15C0GK5UAA | A470K15C0GL5TAA | A470K15C0GL5UAA | A471J15C0GF5TAA | A471J15C0GF5UAA |
| A471J15C0GH5TAA | A471J15C0GH5UAA | A471J15C0GK5TAA | A471J15C0GK5UAA | A471J20C0GL5TAA |
| A471J20C0GL5UAA | A471K15C0GF5TAA | A471K15C0GF5UAA | A471K15C0GH5TAA | A471K15C0GH5UAA |
| A471K15C0GK5TAA | A471K15C0GK5UAA | A471K15X7RF5TAA | A471K15X7RF5UAA | A471K15X7RH5TAA |
| A471K15X7RH5UAA | A471K15X7RK5TAA | A471K15X7RK5UAA | A471K15X7RL5TAA | A471K15X7RL5UAA |
| A471K20C0GL5TAA | A471K20C0GL5UAA | A471M15X7RF5TAA | A471M15X7RF5UAA | A471M15X7RH5TAA |
| A471M15X7RH5UAA | A471M15X7RK5TAA | A471M15X7RK5UAA | A471M15X7RL5TAA | A471M15X7RL5UAA |
| A472J20C0GF5TAA | A472J20C0GF5UAA | A472K15X7RF5TAA | A472K15X7RF5UAA | A472K15X7RH5TAA |
| A472K15X7RH5UAA | A472K15X7RK5TAA | A472K15X7RK5UAA | A472K20C0GF5TAA | A472K20C0GF5UAA |
| A472K20X7RL5TAA | A472K20X7RL5UAA | A472M15X7RF5TAA | A472M15X7RF5UAA | A472M15X7RH5TAA |
| A472M15X7RH5UAA | A472M15X7RK5TAA | A472M15X7RK5UAA | A472M20X7RL5TAA | A472M20X7RL5UAA |
| A473K15X7RF5TAA | A473K15X7RF5UAA | A473K20X7RH5TAA | A473K20X7RH5UAA | A473K20X7RK5TAA |
| A473K20X7RK5UAA | A473M15X7RF5TAA | A473M15X7RF5UAA | A473M20X7RH5TAA | A473M20X7RH5UAA |
| A473M20X7RK5TAA | A473M20X7RK5UAA | A474K20X7RF5TAA | A474K20X7RF5UAA | A560J15C0GF5TAA |
| A560J15C0GF5UAA | A560J15C0GH5TAA | A560J15C0GH5UAA | A560J15C0GK5TAA | A560J15C0GK5UAA |
| A560J15C0GL5TAA | A560J15C0GL5UAA | A560K15C0GF5TAA | A560K15C0GF5UAA | A560K15C0GH5TAA |
| A560K15C0GH5UAA | A560K15C0GK5TAA | A560K15C0GK5UAA | A560K15C0GL5TAA | A560K15C0GL5UAA |
| A561J15C0GF5TAA | A561J15C0GF5UAA | A561J15C0GH5TAA | A561J15C0GH5UAA | A561J15C0GK5TAA |
| A561J15C0GK5UAA | A561J20C0GL5TAA | A561J20C0GL5UAA | A561K15C0GF5TAA | A561K15C0GF5UAA |
| A561K15C0GH5TAA | A561K15C0GH5UAA | A561K15C0GK5TAA | A561K15C0GK5UAA | A561K15X7RF5TAA |
| A561K15X7RF5UAA | A561K15X7RH5TAA | A561K15X7RH5UAA | A561K15X7RK5TAA | A561K15X7RK5UAA |
| A561K15X7RL5TAA | A561K15X7RL5UAA | A561K20C0GL5TAA | A561K20C0GL5UAA | A561M15X7RF5TAA |
| A561M15X7RF5UAA | A561M15X7RH5TAA | A561M15X7RH5UAA | A561M15X7RK5TAA | A561M15X7RK5UAA |



Product Change Notification



Product Group: CC/Mon Jan 22, 2024/PCN-CC-00002-2024-REV-0

The DNA of tech.™

| | | | | |
|-----------------|-----------------|-----------------|-----------------|-----------------|
| A561M15X7RL5TAA | A561M15X7RL5UAA | A562J20C0GF5TAA | A562J20C0GF5UAA | A562K15X7RF5TAA |
| A562K15X7RF5UAA | A562K15X7RH5TAA | A562K15X7RH5UAA | A562K15X7RK5TAA | A562K15X7RK5UAA |
| A562K20C0GF5TAA | A562K20C0GF5UAA | A562K20X7RL5TAA | A562K20X7RL5UAA | A562M15X7RF5TAA |
| A562M15X7RF5UAA | A562M15X7RH5TAA | A562M15X7RH5UAA | A562M15X7RK5TAA | A562M15X7RK5UAA |
| A562M20X7RL5TAA | A562M20X7RL5UAA | A563K15X7RF5TAA | A563K15X7RF5UAA | A563K20X7RH5TAA |
| A563K20X7RH5UAA | A563M15X7RF5TAA | A563M15X7RF5UAA | A563M20X7RH5TAA | A563M20X7RH5UAA |
| A680J15C0GF5TAA | A680J15C0GF5UAA | A680J15C0GH5TAA | A680J15C0GH5UAA | A680J15C0GK5TAA |
| A680J15C0GK5UAA | A680J15C0GL5TAA | A680J15C0GL5UAA | A680K15C0GF5TAA | A680K15C0GF5UAA |
| A680K15C0GH5TAA | A680K15C0GH5UAA | A680K15C0GK5TAA | A680K15C0GK5UAA | A680K15C0GL5TAA |
| A680K15C0GL5UAA | A681J15C0GF5TAA | A681J15C0GF5UAA | A681J15C0GH5TAA | A681J15C0GH5UAA |
| A681J15C0GK5TAA | A681J15C0GK5UAA | A681J20C0GL5TAA | A681J20C0GL5UAA | A681K15C0GF5TAA |
| A681K15C0GF5UAA | A681K15C0GH5TAA | A681K15C0GH5UAA | A681K15C0GK5TAA | A681K15C0GK5UAA |
| A681K15X7RF5TAA | A681K15X7RF5UAA | A681K15X7RH5TAA | A681K15X7RH5UAA | A681K15X7RK5TAA |
| A681K15X7RK5UAA | A681K15X7RL5TAA | A681K15X7RL5UAA | A681K20C0GL5TAA | A681K20C0GL5UAA |
| A681M15X7RF5TAA | A681M15X7RF5UAA | A681M15X7RH5TAA | A681M15X7RH5UAA | A681M15X7RK5TAA |
| A681M15X7RK5UAA | A681M15X7RL5TAA | A681M15X7RL5UAA | A682K15X7RF5TAA | A682K15X7RF5UAA |
| A682K15X7RH5TAA | A682K15X7RH5UAA | A682K15X7RK5TAA | A682K15X7RK5UAA | A682K20X7RL5TAA |
| A682K20X7RL5UAA | A682M15X7RF5TAA | A682M15X7RF5UAA | A682M15X7RH5TAA | A682M15X7RH5UAA |
| A682M15X7RK5TAA | A682M15X7RK5UAA | A682M20X7RL5TAA | A682M20X7RL5UAA | A683K15X7RF5TAA |
| A683K15X7RF5UAA | A683K20X7RH5TAA | A683K20X7RH5UAA | A683M15X7RF5TAA | A683M15X7RF5UAA |
| A683M20X7RH5TAA | A683M20X7RH5UAA | A820J15C0GF5TAA | A820J15C0GF5UAA | A820J15C0GH5TAA |
| A820J15C0GH5UAA | A820J15C0GK5TAA | A820J15C0GK5UAA | A820J15C0GL5TAA | A820J15C0GL5UAA |
| A820K15C0GF5TAA | A820K15C0GF5UAA | A820K15C0GH5TAA | A820K15C0GH5UAA | A820K15C0GK5TAA |
| A820K15C0GK5UAA | A820K15C0GL5TAA | A820K15C0GL5UAA | A821J15C0GF5TAA | A821J15C0GF5UAA |
| A821J15C0GH5TAA | A821J15C0GH5UAA | A821J15C0GK5TAA | A821J15C0GK5UAA | A821J20C0GL5TAA |
| A821J20C0GL5UAA | A821K15C0GF5TAA | A821K15C0GF5UAA | A821K15C0GH5TAA | A821K15C0GH5UAA |
| A821K15C0GK5TAA | A821K15C0GK5UAA | A821K15X7RF5TAA | A821K15X7RF5UAA | A821K15X7RH5TAA |
| A821K15X7RH5UAA | A821K15X7RK5TAA | A821K15X7RK5UAA | A821K15X7RL5TAA | A821K15X7RL5UAA |
| A821K20C0GL5TAA | A821K20C0GL5UAA | A821M15X7RF5TAA | A821M15X7RF5UAA | A821M15X7RH5TAA |
| A821M15X7RH5UAA | A821M15X7RK5TAA | A821M15X7RK5UAA | A821M15X7RL5TAA | A821M15X7RL5UAA |
| A822K15X7RF5TAA | A822K15X7RF5UAA | A822K15X7RH5TAA | A822K15X7RH5UAA | A822K15X7RK5TAA |
| A822K15X7RK5UAA | A822K20X7RL5TAA | A822K20X7RL5UAA | A822M15X7RF5TAA | A822M15X7RF5UAA |
| A822M15X7RH5TAA | A822M15X7RH5UAA | A822M15X7RK5TAA | A822M15X7RK5UAA | A822M20X7RL5TAA |
| A822M20X7RL5UAA | A823K15X7RF5TAA | A823K15X7RF5UAA | A823K20X7RH5TAA | A823K20X7RH5UAA |
| A823M15X7RF5TAA | A823M15X7RF5UAA | A823M20X7RH5TAA | A823M20X7RH5UAA | |