## Mechanical handheld tachometer

HTM-100M ATEX



## Application:

For contact measurement of rotation speed and surface velocity in environments with a potentially explosive atmosphere.

## Version:

- Large analogue display
- Button-actuated pointer lock for saving the last measurement
- Battery-free operation
- Suitable for ATEX zones 1 and 2
- Plastic housing

## **Delivery:**

Tachometer, measuring wheel (0.1 m), measuring tip, hollow measuring tip, extension, operating instructions

| Art. no.   | 39330 110 |
|--|-----------|
| Max. rotation speed of measuring range (contact) | 10 rpm    |
| Error limit (%)                                  | 0.5 %     |

