

## Global Change Notification (GCN)

Product Family	KK396	10701809
		GCN Number
Series	42491	July 21, 2015
		Date Issued
Reason For Change	MOQ (Not SPQ)	
Change Description	This letter is to inform you that Molex Incorporated is changing the Minimum Order Quantity (MOQ) to match master carton quantity to reduce the possibility of packaging damage at the KK product listen below.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Not Applicable	
Assessment Of Change (How Product Will Be Qualified & Validated)	Optimize packaging.	
Internal Molex Qualification Date (Planned Date Information Available)	January 02, 2016	
Sample Availability Date (Changed Part)	January 02, 2016	
Date of Implementation	January 21, 2016	
Method of Identifying Change	New minimum order quantity	
Recommended Replacement Parts	NA	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)