



## **PRODUCT / PROCESS CHANGE NOTIFICATION (PCN)**

PCN Number:	SC164305					
Notification Subject:	CCB 2733.01 Final Notice: Implement Catalog Part Number (CPN) Changes to Atmel products					
PCN Issue Date:	December 13, 2016					
Change Category:	Logistics					
PCN Status:	Final notification					
Microchip/Atmel Parts Affected:	This change applies to virtually all Atmel products.					
Description of Change:	Implement Catalog Part Number (CPN) convention changes to Atmel products. Please make the necessary revisions to ensure flawless order/entry and receipt of your products.					
Pre and Post Change Information:	Please see the attached affected catalog part number (CPN) list to identify the products affected and changes between the current and new catalog part numbers.					
	Note: Many of the current parts required an additional code after the catalog part number, referred to as the SL code, which some customers may have been unaware of when ordering. To ensure accuracy after the implementation date please query your local sales office with questions if the part number you order is the same as the catalog part number identified in the first column of the attached files.					
Impacts to Data Sheet:	None					
Change Impact:	None					
Reason for Change:	To improve productivity as part of the integration of Atmel and Microchip.					
Change Implementation Status:	In progress					





## Implementation Date:

January 1, 2017

Time	Table	Summary:
LIIIIC	Ianc	Summary.

	:	September 2016			October 2016				→	Januar 2017	
Workweek	36	37	38	39	40	41	42	43	44		1
Final PCN Issue									X		
Date									Х		
Anticipated											
Implementation											Х
Date											

Qualification Report:	Not Applicable
qualification reports	riot / tppiloubio

Data Sheet:

Change:

**Revision History:** 

Method to Identify

October 27, 2016: Issued final notification. December 13, 2016: Revised the final notification to include additional line items and revise existing line items in the affected parts list. The additions and revision fields are highlighted and font is bold. Please review the attached affected parts list.

To view the applicable data sheet please go to the document

Please contact your local Microchip or Atmel Sales Office or Distributor with questions or concerns regarding this notification.

library found on atmel.com