

Product Family	Mini-fit	10653559	
		GCN Number	
Series	5569	October 09, 2014	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	This letter is to inform you that the existing tooling to make 5569-086/081 housings is worn beyond repair and will be replaced by new tooling.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	Product produced by the new tooling will be fully qualified by Molex before it is released to production.		
Internal Molex Qualification Date (Planned Date Information Available)	January 29, 2015		
Sample Availability Date (Changed Part)	January 29, 2015		
Date of Implementation	March 15, 2015		
Method of Identifying Change	Product shipped after March 15, 2015 could contain housings from the new tooling		
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com