



# Product Change Notification

Current Date: 01-May-2022

## TE Connectivity

**Product Change Notification:** P-22-022592

**PCN Date:** 29-APR-22

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Manufacturing Location Change - Dual Source: Guangdong, China / Batangas, Philippines

### Description of Changes

Please be informed that effective beginning September 2022 the following products currently manufactured at the TE Guangdong, China facility may also be sourced from the TE Tanauan, Batangas, Philippines facility. Please contact your TE Account Manager with questions.

### Reason for Changes:

In-line with TE Connectivity's dedication to provide excellent customer service and delivery, we are updating our business continuity plans to include dual-sourcing for select parts.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	30-SEP-2022
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-353293-0</a>	NO		TYC1-353293-0				
<a href="#">173977-2</a>	NO		TYC173977-2	"200058", "15-0167"			
<a href="#">173977-3</a>	NO		TYC173977-3				
<a href="#">173977-8</a>	NO		TYC173977-8				
<a href="#">292132-2</a>	NO		TYC292132-2				
<a href="#">292161-2</a>	NO		TYC292161-2				
<a href="#">292161-7</a>	NO		TYC292161-7				
<a href="#">292161-8</a>	NO		TYC292161-8				
<a href="#">292161-9</a>	NO		TYC292161-9				
<a href="#">292207-8</a>	NO		TYC292207-8				
<a href="#">353293-3</a>	NO		TYC353293-3				
<a href="#">353293-8</a>	NO						



# Product Change Notification

Current Date: 01-May-2022

## TE Connectivity

**Product Change Notification:** P-22-022592

**PCN Date:** 29-APR-22

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Manufacturing Location Change - Dual Source: Guangdong, China / Batangas, Philippines

### Description of Changes

Please be informed that effective beginning September 2022 the following products currently manufactured at the TE Guangdong, China facility may also be sourced from the TE Tanauan, Batangas, Philippines facility. Please contact your TE Account Manager with questions.

### Reason for Changes:

In-line with TE Connectivity's dedication to provide excellent customer service and delivery, we are updating our business continuity plans to include dual-sourcing for select parts.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	30-SEP-2022
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-353293-0</a>	NO		TYC1-353293-0				
<a href="#">173977-2</a>	NO		TYC173977-2	"200058", "15-0167"			
<a href="#">173977-3</a>	NO		TYC173977-3				
<a href="#">173977-8</a>	NO		TYC173977-8				
<a href="#">176394-2</a>	NO						
<a href="#">292132-2</a>	NO		TYC292132-2				
<a href="#">292161-2</a>	NO		TYC292161-2				
<a href="#">292161-7</a>	NO		TYC292161-7				
<a href="#">292161-8</a>	NO		TYC292161-8				
<a href="#">292161-9</a>	NO		TYC292161-9				
<a href="#">292207-8</a>	NO		TYC292207-8				
<a href="#">353293-3</a>	NO		TYC353293-3				
<a href="#">353293-8</a>	NO						