



Product Change Notification

Current Date: 31-May-2019

TE Connectivity

Product Change Notification: E-19-008340

PCN Date: 27-MAY-19

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
SR2 2 pole Force Guided Relay

Description of Changes
TE Connectivitys (TE) SR2M 2 pole Force Guided Relay have a China Compulsory Certificate (CCC) mark of product certification. The Chinese Certification and Accreditation Authority (CNCA) has published new Implementation Rules for Compulsory Certification requiring reapproval by CCC. TE has been informed by CCC that as of May 8th, 2019 the certificate has been suspended. TE is expected to regain the CCC approval during the week of July 15 - 19, 2019. Until the product is recertified, TE will remove the CCC marking from the Force Guided Relay products SR2 effective with May 27,2019. TE will notify our customers when we can apply the CCC mark to our Force Guided Relay products again which is expected in the week of July 15 - 19, 2019.

Reason for Changes:				
Document Clarification.				
Estimated Dates:				
<table border="1"><tr><td>Last Order Date (Obsolete Parts Only):</td><td>First Date To Ship (Changed Parts Only):</td></tr><tr><td></td><td>28-MAY-2019</td></tr></table>	Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		28-MAY-2019
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
	28-MAY-2019			

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	27-AUG-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO			"V23047-A1021-A501", "V23047A1021A501"			
1-1393258-2	NO			"V23047-A1021-A511", "V23047A1021A511"			
1-1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			
1-1393258-7	NO			"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			
1-1415012-1	NO			"V23047-A1110-A501", "V23047A1110A501"			
1393258-2	NO			"V23047-A1005-A501", "V23047A1005A501"			
1393258-3	NO			"V23047-A1009-A501", "V23047A1009A501"			
1393258-4	NO			"V23047-A1012-A501", "V23047A1012A501"			
1393258-5	NO			"V23047-A1012-A511", "V23047A1012A511"			
2-1415012-1	NO			"V23047-A1110-A511", "V23047A1110A511"			

3-1415006-1	NO			"V23047-A1048-A501", "V23047A1048A501"			
7-1415006-1	NO			"V23047-A1005-A511", "V23047A1005A511"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO		TYC1-1393258-1	"V23047-A1021-A501", "V23047A1021A501"			
1-1393258-2	NO			"V23047-A1021-A511", "V23047A1021A511"			
1-1393258-5	NO		TYC1-1393258-5	"V23047-A1024-A501", "V23047A1024A501"			
1-1393258-7	NO		TYC1-1393258-7	"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			
1-1415012-1	NO		TYC1-1415012-1	"V23047-A1110-A501", "V23047A1110A501"			
1393258-2	NO		TYC1393258-2	"V23047-A1005-A501", "V23047A1005A501"			
1393258-3	NO		TYC1393258-3	"V23047-A1009-A501", "V23047A1009A501"			
1393258-4	NO		TYC1393258-4	"V23047-A1012-A501", "V23047A1012A501"			

1393258-5	NO		TYC1393258-5	"V23047-A1012-A511", "V23047A1012A511"			
3- 1415006-1	NO		TYC3-1415006-1	"V23047-A1048-A501", "V23047A1048A501"			
7- 1415006-1	NO		TYC7-1415006-1	"V23047-A1005-A511", "V23047A1005A511"			

Customer: TTI Electronics Asia Pte Ltd (1407161)

Location: Kowloon Bay

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393258-4	NO			"V23047-A1012-A501", "V23047A1012A501"			

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			
1- 1393258-7	NO			"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			

Customer: TTI Electronics Asia Pte Ltd (3063486)

Location: Taipei

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393258-4	NO			"V23047-A1012-A501", "V23047A1012A501"			

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			

1-1393258-7	NO			"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			
1393258-2	NO			"V23047-A1005-A501", "V23047A1005A501"			
2-1415012-1	NO			"V23047-A1110-A511", "V23047A1110A511"			

Customer: TTI, Inc. (3057778)

Location: Maisach-germlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO		TYC1-1393258-1	"V23047-A1021-A501", "V23047A1021A501"			
1-1393258-2	NO			"V23047-A1021-A511", "V23047A1021A511"			
1-1393258-5	NO		TYC1-1393258-5	"V23047-A1024-A501", "V23047A1024A501"			
1-1393258-7	NO		TYC1-1393258-7	"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			
1-1415012-1	NO		TYC1-1415012-1	"V23047-A1110-A501", "V23047A1110A501"			
1393258-2	NO		TYC1393258-2	"V23047-A1005-A501", "V23047A1005A501"			

1393258-3	NO		TYC1393258-3	"V23047-A1009-A501", "V23047A1009A501"			
1393258-4	NO		TYC1393258-4	"V23047-A1012-A501", "V23047A1012A501"			
1393258-5	NO		TYC1393258-5	"V23047-A1012-A511", "V23047A1012A511"			
3- 1415006-1	NO		TYC3-1415006-1	"V23047-A1048-A501", "V23047A1048A501"			