



Product Change Notification

Current Date: 28-Jun-2021

TE Connectivity

Product Change Notification: E-21-006540

PCN Date: 25-JUN-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

CPC Connectors

Description of Changes

Change the method of marking the contact cavity identification numbers on the wire entry end of the connector from white ink stamping to laser marking.

Reason for Changes:

Manufacturing / Process Requirements. The tooling used to white ink stamp is damaged and unable to be repaired or replaced. For this reason the change is being implemented immediately.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

05-JUL-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
796188-1	NO						
796190-1	NO						
796271-1	NO						
796274-1	NO						
796275-1	NO						



Product Change Notification

Current Date: 28-Jun-2021

TE Connectivity

Product Change Notification: E-21-006540

PCN Date: 25-JUN-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

CPC Connectors

Description of Changes

Change the method of marking the contact cavity identification numbers on the wire entry end of the connector from white ink stamping to laser marking.

Reason for Changes:

Manufacturing / Process Requirements. The tooling used to white ink stamp is damaged and unable to be repaired or replaced. For this reason the change is being implemented immediately.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	05-JUL-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
796188-1	NO		TYC796188-1				
796190-1	NO		TYC796190-1				
796274-1	NO		TYC796274-1				
796275-1	NO		TYC796275-1				