## Product Change Notification

Current Date: 27-Feb-2015

# **TE Connectivity**

### Product Change Notification: E-15-002423

Customer: Premier Farnell UK Ltd (PFUK) (101113)

Location: Leeds

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

#### General Product Description:

1410187-X Right angle plug assembly, 7 Row, 20.3mm Multigig

#### Description of Changes

TE production Drawing 1410187-X is missing the arrows pointer at the wafers location in Zones D7 and D8. There have been no changes to the existing parts, this is a revision increase only.

Reason for Changes:						
Document Clarification. Software glitched, it caused the TE PD 1410187-X missed the arrows pointer in Zone D7 and D8.						
Estimated Dates:						
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):					
	02-MAR-2015					
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):					
	27-MAR-2015					

#### Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>1410187-3</u>	NO		1329934				



### PCN Date: 26-FEB-15