

Change Notification

Process Change Notification #: PCN-000202 Date Issued: **12/25/2013**

Semtech Corporation is providing this Change Notification to our customers notifying the qualification of copper wire bonding at our assembly & test supplier. This change affects the following product.

Rclamp0521PATCT

Semtech's Change Evaluation Team has classified this change as major. Specifically, the supplier Diodes has qualified 0.8 mil copper wire to replace 0.8 mil gold wire. This will result in no change to form, fit, function, and reliability or datasheet specifications. Semtech has completed reliability testing of this part number and it meets Semtech's reliability requirements. Semtech's qualification was completed on September, 23 2013. (Ref: Reliability test report # 5609).

It is Semtech's intention to implement this change to the aforementioned product March 25, 2014 pursuant to the notification guidelines of JEDEC 46. Samples are currently available.

If you wish to acquire samples, please do not hesitate to contact your local Semtech sales representative. The samples will be available now. If you have any questions regarding our qualification requirements, do not hesitate to give me a call.

Pat Sanchez Manager, Corporate Quality

200 Flynn Road Camarillo, CA 93012

psanchez@semtech.com

Office: (805) 480-2074 Fax: (805) 498-3804

by Sublot, by Sequence Contact: Gurmail Sajjan (805) 480 2142 gsajjan@semtech.com

Businessunit	Protection				
Reljob#	Part_Number, Job Name/Type	Fab, Package	Rel Job Status	Key Dates:	
5609	RClamp0521PA	ASMC21 TVS	Rel Testing Complete	Job Accepted: 12-Jul-2013	
	Package qual (with 0.8 mil Cu wirebond & W	SLP1006P2	Passes All Requirements	Requested CD:	
	New Product on qualified process with unqualified package			Actual Start Date: 18-Jun-2013	
			•	ECD for Conditional:	
				Job ECD: 09-Sep-2013	

Completed Tasks

Wednesday, October 02, 2013

Page 1 of 7

by Sublot, by Sequence Contact: Gurmail Sajjan (805) 480 2142 gsajjan@semtech.com

4.0	Lot GDA121200A	AssemblyLor	<i>t</i> AER-001162	DateCode	1323			
	Seq TaskCode		SampleSize	Criteria	Complete	Failures	DataSource	Results/Comments
	1 Data-Prep		None	None	03-Jul-2013		Camarillo	
	2 HTRB_Pre_Elect_150°C	_RT24	210		02-Aug-2013	0	Camarillo	
	3 HTRB_150°C_Real Time	e_0024	210	Pass on Zero Fails	30-Aug-2013	0	Camarillo	
	4 HTRB_Pre_Elect		105	Pass on Zero Fails	05-Jul-2013	0	Camarillo	
	5 HTRB_150°C_0072		105	Pass on Zero Fails	08-Jul-2013	0	Camarillo	
	6 HTRB_150°C _0408		105	Pass on Zero Fails	25-Jul-2013	0	Camarillo	
	7 HTS_Pre_Elect		77	Pass on Zero Fails	05-Jul-2013	0	Camarillo	
	8 HTS_0168		77	Pass on Zero Fails	15-Jul-2013	0	Camarillo	
	9 HTS_0500		77	Pass on Zero Fails	26-Jul-2013	0	Camarillo	
	10 HTS_1000		77	Pass on Zero Fails	16-Aug-2013	0	Camarillo	
	12 Pre_Elect_Precond		154	Pass on Zero Fails	16-Jul-2013	0	Camarillo	
	13 Precond_Temp_Cyc_5cy	/c	154	Pass on Zero Fails	16-Jul-2013	0	Camarillo	
	14 Precond_HTS_24hr		154	Pass on Zero Fails	17-Jul-2013	0	Camarillo	
	15 Precond_85/85_NoElec1	68hr	154	Pass on Zero Fails	24-Jul-2013	0	Camarillo	
	16 Precond_IR_Refl_Char		154	Pass on Zero Fails	24-Jul-2013	0	Camarillo	
	17 T/C_Pre_Elect		77	Pass on Zero Fails	24-Jul-2013	0	Camarillo	
	18 T/C_wPre_0250		77	Pass on Zero Fails	30-Jul-2013	0	Camarillo	
	19 T/C_wPre_0500		77	Pass on Zero Fails	07-Aug-2013	0	Camarillo	
	20 T/C_wPre_1000		77	Pass on Zero Fails	13-Aug-2013	0	Camarillo	
	21 HAST Pre_Elect		77	Pass on Zero Fails	24-Jul-2013	0	Camarillo	
	22 HAST_BD_Validation		N/A	Pass on Zero Fails	02-Aug-2013	0	Camarillo	
	23 HAST_wPRE_0200		77	Pass on Zero Fails	14-Aug-2013	0	Camarillo	
	24 Pack_Clos		0	0	29-Aug-2013		Camarillo	

Wednesday, October 02, 2013

Page 5 of 7

by Sublot, by Sequence Contact: Gurmail Sajjan (805) 480 2142 gsajjan@semtech.com

.0 Lot GDA121200A Asset	mblyLot AER-001163	DateCode	1323			
Seq TaskCode	SampleSize	Criteria	Complete	Failures	DataSource	Results/Comments
1 Data-Prep	None	None	03-Jul-2013		Camarillo	
2 HTRB_Pre_Elect_150°C_RT24	210		02-Aug-2013	0	Camarillo	
3 HTRB_150°C_Real Time_0024	210	Pass on Zero Fails	04-Sep-2013	0	Camarillo	
4 HTRB_Pre_Elect	105	Pass on Zero Fails	05-Jul-2013	0	Camarillo	
5 HTRB_150°C_0072	105	Pass on Zero Fails	08-Jul-2013	0	Camarillo	
6 HTRB_150°C _0408	105	Pass on Zero Fails	25-Jul-2013	0	Camarillo	
7 HTS_Pre_Elect	77	Pass on Zero Fails	05-Jul-2013	0	Camarillo	
8 HTS_0168	77	Pass on Zero Fails	15-Jul-2013	0	Camarillo	
9 HTS_0500	77	Pass on Zero Fails	26-Jul-2013	0	Camarillo	
10 HTS_1000	77	Pass on Zero Fails	16-Aug-2013	0	Camarillo	
12 Pre_Elect_Precond	154	Pass on Zero Fails	29-Jul-2013	0	Camarillo	
13 Precond_Temp_Cyc_5cyc	154	Pass on Zero Fails	29-Jul-2013	0	Camarillo	
14 Precond_HTS_24hr	154	Pass on Zero Fails	30-Jul-2013	0	Camarillo	
15 Precond_85/85_NoElec168hr	154	Pass on Zero Fails	06-Aug-2013	0	Camarillo	
16 Precond_IR_Refl_Char	154	Pass on Zero Fails	06-Aug-2013	0	Camarillo	
17 T/C_Pre_Elect	77	Pass on Zero Fails	06-Aug-2013	0	Camarillo	
18 T/C_wPre_0250	77	Pass on Zero Fails	12-Aug-2013	0	Camarillo	
19 T/C_wPre_0500	77	Pass on Zero Fails	20-Aug-2013	0	Camarillo	
20 T/C_wPre_1000	77	Pass on Zero Fails	27-Aug-2013	0	Camarillo	
21 HAST Pre_Elect	77	Pass on Zero Fails	06-Aug-2013	0	Camarillo	
22 HAST_BD_Validation	N/A	Pass on Zero Fails	09-Aug-2013	0	Camarillo	
23 HAST_wPRE_0200	77	Pass on Zero Fails	19-Aug-2013	0	Camarillo	
24 Pack_Clos	0	0	06-Sep-2013		Camarillo	

Wednesday, October 02, 2013

Page 6 of 7

by Sublot, by Sequence Contact: Gurmail Sajjan (805) 480 2142 gsajjan@semtech.com

.0 Lot GDA121200A Assem	ablyLot AER-001164	DateCode	1323		
Seq TaskCode	SampleSize	Criteria	Complete	Failures	DataSource Results/Comments
1 Data-Prep	None	None	03-Jul-2013		Camarillo
2 HTRB_Pre_Elect_150°C_RT24	210		02-Aug-2013	0	Camarillo
3 HTRB_150°C_Real Time_0024	210	Pass on Zero Fails	05-Sep-2013	0	Camarillo
4 HTRB_Pre_Elect	105	Pass on Zero Fails	05-Jul-2013	0	Camarillo
5 HTRB_150°C_0072	105	Pass on Zero Fails	08-Jul-2013	0	Camarillo
6 HTRB_150°C _0408	105	Pass on Zero Fails	25-Jul-2013	0	Camarillo
7 HTS_Pre_Elect	77	Pass on Zero Fails	05-Jul-2013	0	Camarillo
8 HTS_0168	77	Pass on Zero Fails	15-Jul-2013	0	Camarillo
9 HTS_0500	77	Pass on Zero Fails	26-Jul-2013	0	Camarillo
10 HTS_1000	77	Pass on Zero Fails	16-Aug-2013	0	Camarillo
12 Pre_Elect_Precond	154	Pass on Zero Fails	29-Jul-2013	0	Camarillo
13 Precond_Temp_Cyc_5cyc	154	Pass on Zero Fails	29-Jul-2013	0	Camarillo
14 Precond_HTS_24hr	154	Pass on Zero Fails	30-Jul-2013	0	Camarillo
15 Precond_85/85_NoElec168hr	154	Pass on Zero Fails	06-Aug-2013	0	Camarillo
16 Precond_IR_Refl_Char	154	Pass on Zero Fails	06-Aug-2013	0	Camarillo
17 T/C_Pre_Elect	77	Pass on Zero Fails	06-Aug-2013	0	Camarillo
18 T/C_wPre_0250	77	Pass on Zero Fails	12-Aug-2013	0	Camarillo
19 T/C_wPre_0500	77	Pass on Zero Fails	20-Aug-2013	0	Camarillo
20 T/C_wPre_1000	77	Pass on Zero Fails	27-Aug-2013	0	Camarillo
21 HAST Pre_Elect	77	Pass on Zero Fails	06-Aug-2013	0	Camarillo
22 HAST_BD_Validation	N/A	Pass on Zero Fails	09-Aug-2013	0	Camarillo
23 HAST_wPRE_0200	77	Pass on Zero Fails	19-Aug-2013	0	Camarillo
24 Pack_Clos	0	0	06-Sep-2013		Camarillo

Wednesday, October 02, 2013

Page 7 of 7