

Product Change Notification

Current Date: 14-Jul-2022

TE Connectivity

Product Change Notification: PCN-22-143739 PCN Date: 14-JUL-22

Customer: TTI Inc (168830) Location: Fort Worth Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: (Text limited to 120 characters)
Terminal Contacts

Description of Changes

Please be aware that the packaging reel is being changed for the following mentioned part numbers. Please refer to attached document for details. Other attachments:

Reference Document

Reason for Changes:

PCN Attributes:			
Product Category:	Kind of Change:		
Terminals	Packaging Type		
Change Feature:	Potential Customer Impact:		
Reel	No Customer Impact		
Remarks:			

Estimated Dates:		
Last Order Date (Obsolete Parts Only): First Ship Date of Changed Items (Changed Parts Only):		
	03-OCT-2022	
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):	
	No Mixed Shipments	
Effectivity Date:	Date of First Samples:	

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
11202	NO						
<u> 11274</u>	NO						
11330	NO			"668-1036-02"			
11332	NO						
11333	NO						
<u> 42100-2</u>	NO						
<u>12400-1</u>	NO						
42801-1	NO						
50196-1	NO						
501 <u>9</u> 7-1	NO						
51283-1	NO			"0-0061283-1"			
51436-1	NO						
53306-1	NO						
53477-2	NO						
640051-1	NO						
640052-1	NO						
640253-2	NO						





Paper reel change from 999225-1 to 2400473-1





Paper reel appearance status 999225-1 & 2400473-1

Before

Reel part	Reel status	Fixed method	Different
995225-1	STE CONNECTIVITY OF STATE OF	3024618 07 5	1. No hole 2. Fixed of FIBER TAPE

Note:

- 1. Paper core status is different
- 2. Fixed method is different
- 3. Flag have small change, two side the circular hole change to the rectangle hole

After

Reel part	Reel status	Fixed method	Different
2400473-1	C: 0, 2400473-1 00.21/22		Hole on the core Fixed of core hole



Thanks

