



Product Change Notification

Current Date: 08-Mar-2021

TE Connectivity

Product Change Notification: E-21-002238

PCN Date: 08-MAR-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
2000676-X MULTIGIG Guide pin hardware

Description of Changes
There was a typo on customer DWg 2000676-X. Remove figure 2000676-6 in Zone A6 and A7. Adding 2000676-6 to figure in zone D5 and D6.

Reason for Changes: Document Clarification. Clarification	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-MAR-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-APR-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2000676-2	NO		1G37-019, TYC2000676-2, 53500811-6				
2000676-7	NO		TYC2000676-7				

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
2000676	2000676-2	1G37-019, TYC2000676-2, 53500811-6	M	



Product Change Notification

Current Date: 08-Mar-2021

TE Connectivity

Product Change Notification: E-21-002238

PCN Date: 08-MAR-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
2000676-X MULTIGIG Guide pin hardware

Description of Changes
There was a typo on customer DWg 2000676-X. Remove figure 2000676-6 in Zone A6 and A7. Adding 2000676-6 to figure in zone D5 and D6.

Reason for Changes:	
Document Clarification. Clarification	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-MAR-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-APR-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2000676-7	NO		TYC2000676-7				