

# INFORMATION NOTE



N° 017/21

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

**Functional Safety related Information Note:  
Safety Manual Update V1.12 affecting products TC3xx**

Infineon Technologies AG  
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0  
Chairman of the Supervisory Board: Dr. Wolfgang Eder  
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider  
Registered Office: Neubiberg  
Commercial Register: München HRB 126492

# INFORMATION NOTE



N° 017/21

## Functional Safety related Information Note: Safety Manual Update V1.12 affecting products TC3xx

► **Products affected:**

Please refer to attached affected product list 1\_cip01721

► **Detailed Change Information:**

**Subject:** AURIX TC3xx Safety Manual v1.12

**Reason:** Safety Manual Version update

**Description:**

Old

- Safety Manual V1.11

New

- Safety Manual V1.12

► **Product Identification:**

Not applicable (no change of product)

► **Impact of Change:**

Assessment in application required !

► **Attachments:**

Affected product list 1\_cip01721

Safety Manual V1.12 (link):

[https://myicp.infineon.com/sites/microcontrollers-aurix\\_customer\\_doc/Lists/defaultdoclib/AURIX%20TC3xx/00%20AURIX%20TC3xx%20General/02%20Safety%20Documentation/AURIX\\_TC3xx\\_Safety\\_Manual\\_V1\\_12.zip](https://myicp.infineon.com/sites/microcontrollers-aurix_customer_doc/Lists/defaultdoclib/AURIX%20TC3xx/00%20AURIX%20TC3xx%20General/02%20Safety%20Documentation/AURIX_TC3xx_Safety_Manual_V1_12.zip)

**In case you don't have access, please contact your local Sales/ FAE**

► **Intended start of delivery:**

Not applicable

If you have any questions, please do not hesitate to contact your local Sales office.