



06-Nov-2018

PCN #:P-18-016545

Subject:8POS,AMP MCP1.5K,REC. HSG,CODA

Description of Change: Manufacturing location change (Extension of manufacturing location for second source). Following Part Numbers of HDSCS Rec Housing Group D, PN1-1418479-1 , from TE Woert Germany to Supplier.

Reason: Part status change. Dear Customer, we hereby inform you about a Manufacturing location change to a 2nd source of manual assembly processes, whereas the components manufacturing location remains in TE. As a result of our continuous strive for capacity increase of our assembly processes. The extension follows a strict procedure, which fully maintains Quality, ability to supply and form-fit-function of the concerned products. The manufactured location operates under s certified Quality Management System in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specification will be executed before delivery. Upon request, a PPAP Level 1 will be available if it concerns a finished TE product, where the production location of the components of the TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Content within 14 calendar days after receipt of this PCN.

Key Dates:

Contact By Date:19-Dec-2018

Implementation Date:19-Dec-2018

Product Affected

1-1418479-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary

from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.