



07-Apr-2023

PCN #: P-23-024375

Subject : EVC250 RELAY

Description of Change : Dear Customer, we hereby inform you about a replacement of the manufacturing mold tool for the TE component part "COVER" of EVC250 RELAY. A tool built at the supplier and part production at the TE Evora.

Reason : Product improvement.As a result of our continuous strive for quality improvements in our production, we hereby inform you upfront about a new tool 21-1962647, which is under construction In order to meet all specification requirements to replace the current one, which is worn out.

Key Dates :

Contact By Date:24-Nov-2023

Implementation Date:24-Nov-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1-1904070-2	"V23720-A0002-X001"		
2-1904136-5	"V23720-A0101-B001"		
2-1904070-2	"V23720-A0001-A001"		
4-1904065-7	"V23720-A0002-A001"		
1-1904070-1	"V23720-A0002-X001"		
7-1904137-6	"V23720-A0102-B001"		
6-1904149-9	"V23720-A0001-X009"		
2347569-1	"V23720-A0001-X012"		
4-1904124-0	"V23720-A0101-X005"		

2-1904136-4	"V23720-A0101-X008"		
2-2317670-1	"V23720-A0112-B001"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.