



Product Change Notification

Current Date: 04-Jun-2021

TE Connectivity

Product Change Notification: PCN-21-102982

PCN Date: 02-JUN-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Contact Terminal

Description of Changes
The listed part numbers will be transferred from TE Connectivity Lickdale plant to US Vendor in order to achieve a greater output and minimize delivery issues caused by the significant increase in demand we are experiencing, which guarantees the performance

| | |
|---|---|
| Reason for Changes: | |
| Internal Requirement | |
| Estimated Dates: | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 27-MAY-2021 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 01-JUN-2021 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1-160655-1 | NO | | TYC1-160655-1 | | | | |
| 160655-2 | NO | | TYC160655-2 | "F49671-000", "AMPS-0-0160655-2" | | | |
| 160655-4 | NO | | TYC160655-4 | | | | |
| 160655-5 | NO | | | | | | |
| 160684-2 | NO | | TYC160684-2 | | | | |
| 160864-2 | NO | | TYC160864-2 | | | | |
| 640417-1 | NO | | TYC640417-1 | | | | |



Product Change Notification

Current Date: 04-Jun-2021

TE Connectivity

Product Change Notification: PCN-21-102982

PCN Date: 02-JUN-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Contact Terminal

Description of Changes
The listed part numbers will be transferred from TE Connectivity Lickdale plant to US Vendor in order to achieve a greater output and minimize delivery issues caused by the significant increase in demand we are experiencing, which guarantees the performance

Reason for Changes:
Internal Requirement

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 27-MAY-2021 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 01-JUN-2021 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1-160655-1 | NO | | TYC1-160655-1 | | | | |
| 160655-2 | NO | | TYC160655-2 | "F49671-000", "AMPS-0-0160655-2" | | | |
| 160655-4 | NO | | TYC160655-4 | | | | |
| 160684-2 | NO | | TYC160684-2 | | | | |
| 640417-1 | NO | | TYC640417-1 | | | | |