

11th January 2021

To: Valued Customer

From: Littelfuse Product Management

Re: 242AT1, 0304, 0305, 04450 & 0460 Fuse Series Product Enhancement

This is a 30-day PCN. PCN # is 11012021P.

With regards to the above reference, we are working to enhance the robustness of our 242 "AT1 version" Fuse Series, 304 Fuse Series, 305 Fuse Series, 04450 Fuse Series & 0460 Fuse Series Pico fuses by replacing the current caps which have welded lead attachments to a more secure and robust riveted cap.

The riveted cap increases the pull strength which enhances the robustness of the fuses.

At the same time, the riveted caps will also help to broaden our supply base and increases our assurance of supply.

There are no changes to the electrical specifications and do not affect the overall dimensions of the current design. Additionally there will be no changes to the part number.

Based on the 30-day PCN, the change will be implemented in production on the 10th February 2021 at the earliest. This will be a running change in production.

Please see attached for the affected part numbers:

| 0242.050HAT1 | 0242.050UAT1M | 0304.250HR | 0305.160H | 0305.080V | 0460.500ER | 0460.375UR |
|--------------|----------------|-------------|-----------|---------------|------------|------------|
| 0242.050UAT1 | 0242.080UAT1M | 0304.500HR | 0305.200H | 0305.100V | 0460.750ER | 0460.500UR |
| 0242.080HAT1 | 0242.100UAT1M | 0304.750HR | 0305.250H | 0305.160V | 0460001.ER | 0460.750UR |
| 0242.080UAT1 | 0242.125UAT1M | 0304.050ZRS | 0305.500H | 0305.200V | 046001.5ER | 0460001.UR |
| 0242.100HAT1 | 0242.160UAT1M | 0304.050ZR | 0305.750H | 0305.250V | 0460002.ER | 046001.5UR |
| 0242.100UAT1 | 0242.200UAT1M | 0304.080ZR | 0305.050M | 0305.500V | 046002.5ER | 0460002.UR |
| 0242.125HAT1 | 0242.250UAT1M | 0304.100ZR | 0305.080M | 0305.750V | 0460003.ER | 046002.5UR |
| 0242.125UAT1 | 0242.100UA851 | 0304.160ZR | 0305.100M | 0305.050H | 046003.5ER | 0460003.UR |
| 0242.160HAT1 | 0242.100UA851M | 0304.200ZR | 0305.160M | 04450070FX850 | 0460004.ER | 046003.5UR |
| 0242.160UAT1 | 0304.050HR | 0304.250ZR | 0305.200M | 04450080FX850 | 0460005.ER | 0460004.UR |
| 0242.200HAT1 | 0304.080HR | 0304.500ZR | 0305.250M | | | 0460005.UR |
| 0242.200UAT1 | 0304.100HR | 0304.750ZR | 0305.500M | | | |
| 0242.250HAT1 | 0304.160HR | 0305.080H | 0305.750M | | | |
| 0242.250UAT1 | 0304.200HR | 0305.100H | 0305.050V | | | |

Please let us know should you have further queries.

Best regards;
Daniel Wang
Director – Global Product Management - OverCurrent
Electronics Business Unit
Littelfuse Far East Pte Ltd
(65) 6885 9199
Dwang@Littelfuse.com