



18-Jan-2023

PCN #: PCN-22-155798

Subject : PCN for RT relays

Description of Change : The following part numbers are being modified due to remove glue at the gate of relay base. This change will improve glue process. This change is just an appearance change, no function and performance influence of relay.

Reason : Product improvement. Dear customer, you are receiving this notice this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. These parts are affected by the change mentioned above.

Key Dates :

Contact By Date:12-Jul-2023

Implementation Date:12-Jul-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1-1649326-4	"RT114018A P"		
2-1649326-4	"RTB34024A P"		
1-1649328-6	"RT314048A P"		
7-1649329-4			
2-1419108-7	"RTB34012F"		
2-1419108-6	"RTB14024F"		
7-1649329-3			
4-1419108-4			
2-1649329-2	"RTE44012A P"		
1649329-6	"RTE24024A P"		
1-1649329-7	"RT424060A P"		

3-1393237-5	"RTE44024F"		
3-1649329-3	"RT444024A P"		
1649357-4	"RTH14012A P"		
3-1393237-3	"RTE24024F"		
3-1419108-1	"RTD14024F"		
3-1649328-4	"RT334048A P"		
1649328-6	"RTD14024A P"		
5-1833004-0	"RTH34012W GAP"		
2-1649329-1	"RTE44009A P"		
6-1393227-5	"RTE24006F"		
1-1649329-2	"RT424009A P"		
3-1649327-3	"RT234024A P"		
3-1649328-7			
1649357-1	"RTH14005A P"		
1-1649327-5	"RT214024A P"		
1649329-8	"RTE24060A P"		
2-1649326-9	"RT134006A P"		
2-1649326-2	"RTB34012A P"		
2-1649329-5	"RTE44048A P"		
4-1419108-9			
4-1649329-0	"RTE25012A P"		
4-1419108-5			
1-1649329-1	"RT424006A P"		
7-1649329-5			
3-1649328-5	"RT334060A P"		
1649326-7	"RTB14048A P"		

3-1393237-0	"RTE24009F"		
5-1833002-1	"RT314024W GAP"		
5-1419108-1			
4-1833002-2			
1-1649328-5	"RT314024A P"		
5-1833004-3			
1-1649326-0	"RT114005A P"		
1649329-5	"RTE24018A P"		
2-1419108-9	"RTD14012F"		
3-1649326-3	"RT134024A P"		
2-1649328-8	"RT334005A P"		
7-1649329-7			
3-1649328-8			
4-1419108-8			
4-1419108-7			
2-1649328-5	"RTD34048A P"		
1649326-6	"RTB14024A P"		
3-1419108-9	"RTD34024F"		
1649328-5	"RTD14018A P"		
5-1833002-0	"RT314012W GAP"		
2-1419108-8	"RTD14005F"		
1649328-8	"RTD14060A P"		
1-1649326-2	"RT114009A P"		
1649326-4	"RTB14012A P"		
1-1649328-1	"RT314006A P"		
1-1649357-3	"RTH34012A P"		
3-1393237-6			

1649328-1	"RTD14005A P"		
4-1419108-2	"RTE44012F"		
1-1649328-2	"RT314009A P"		
1649329-2	"RTE24006A P"		
2-1649328-9	"RT334006A P"		
8-1833003-5			
1-1649327-0	"RT214005A P"		
1-1649328-0	"RT314005A P"		
3-1649326-1	"RT134012A P"		
1-1649328-4	"RT314018A P"		
3-1393237-1	"RTE24012F"		
1-1649357-5	"RTH34024A P"		
4-1419108-0	"RTE24005F"		
3-1393237-4	"RTE24048F"		
2-1419108-5	"RTB14012F"		
2-1649329-4	"RTE44024A P"		
1649328-2	"RTD14006A P"		
4-1419108-6			
1-1649326-7	"RT114060A P"		
3-1649329-4	"RT444048A P"		
4-1833002-1			
2-1649326-3	"RTB34018A P"		
2-1419108-4	"RTB14005F"		
1649327-6	"RTC14024A P"		
1-1649326-1	"RT114006A P"		
1-1649326-6	"RT114048A P"		

1649326-5	"RTB14018A P"		
1-1649327-3	"RT214012A P"		
3-1419108-6	"RTD34012F"		
1-1649328-7	"RT314060A P"		
1649329-1	"RTE24005A P"		
2-1649328-2	"RTD34012A P"		
1-1649328-9	"RTD34005A P"		
1-1649326-3	"RT114012A P"		
1-1649327-1	"RT214006A P"		
4-1833002-0			
2-1649329-9	"RT444006A P"		
3-1649328-1	"RT334012A P"		
1649326-2	"RTB14006A P"		
1649329-4	"RTE24012A P"		
3-1649327-1	"RT234012A P"		
1649328-4	"RTD14012A P"		
1-1649326-5	"RT114024A P"		
1-1649329-9	"RTE44005A P"		
1649326-1	"RTB14005A P"		
1-1649329-4	"RT424018A P"		
1649327-4	"RTC14012A P"		
1-1649329-0	"RT424005A P"		
1-1649329-6	"RT424048A P"		
1649357-6	"RTH14024A P"		

2-1649329-8	"RT444005A P"		
1-1649328-3	"RT314012A P"		
1649329-3	"RTE24009A P"		
3-1649326-4	"RT134048A P"		
7-1649329-6			
5-1833002-3			
3-1649328-3	"RT334024A P"		
2-1649326-8	"RT134005A P"		
1-1649329-5	"RT424024A P"		
3-1649329-1	"RT444012A P"		
2-1649328-4	"RTD34024A P"		
3-1649328-2	"RT334018A P"		
1-1649329-3	"RT424012A P"		
5-1833002-2	"RT334012W GAP"		
1649328-7	"RTD14048A P"		
5-1419108-2			
1649329-7	"RTE24048A P"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.

