### Digital to Analog /Digital to Analog Converter Module



#### DESCRIPTION

The PCF8591 module with I2C interface has 4 analog inputs, 1 analog output and built-in LDR, thermistor and potentiometer.

### PACKAGE INCLUDES:

- PCF8591 A/D and D/A Converter Module
- Qty 4 F/F jumper wires, 8"

### **KEY FEATURES OF PCF8591 A/D AND D/A CONVERTER**

#### MODULE:

- 4-channel 8-bit analog-to-digital conversion inputs
- 1-channel 8-bit digital-to-analog conversion output
- Built-in LDR (Light Detecting Resistor)
- Built-in thermistor

- Built-in potentiometer
- I2C bus
- 3.3V and 5V logic compatible.

This module is basically a reference design to show off some possible applications of the PCF8591 chip. It is a good learning module which incorporates both ADC inputs and a DAC output and includes basic sensors in a nice small inexpensive package. It also has some practical use in projects that can make use of the built-in features.

## **DAC Analog Output**

The DAC output is connected to pin **AOUT**.

The 8-bit single output provides 256 steps of resolution. For a VCC of 5V, the step size will be 5V/256 = 20mV.

The DAC output has a modest current capability to begin with and also has a 1K resistor and LED hooked up to it. The LED makes it easy to see the affect of changing the analog output for experimenting, but for use in actual applications it limits the output swing from reaching full Vcc. If Vcc is 5V, it will max out at about 4.2V. For applications that need the full GND to Vcc swing of the DAC output it is recommended to remove the LED to avoid the extra load on the output.

The DAC is also used internally by the ADC inputs. If using the DAC output, a trackand-hold circuit keeps the value that was set on the output pin while the DAC circuit is being used by the ADC circuit.

# **ADC Analog Inputs**

The 4 analog inputs connect to the header pins **AIN0-AIN3** and can be used as 4 general purpose analog inputs. By default these are 4 single-ended inputs referenced to ground. The PCF8591 chip also supports using them as 2 differential inputs. Refer to the datasheet for specifics on using that mode.

There are 3 jumpers installed on the module that alternatively connects an on-board LDR, thermistor and potentiometer to 3 of these 4 inputs as follows. If you want to use those inputs as general purpose inputs, the jumper should be removed from



that location.

- **J5** Connects LDR to channel 0 (**AIN0**)
- J4 Connects thermistor to channel 1 (AIN1)
- J6 Connects the potentiometer to channel 3 (AIN3)

Note that channel 2 (**AIN2**) does not have an alternate purpose, so no jumper is necessary.



**LDR** – The Light Detecting Resistor (LDR) can detect basic

changes in the intensity of the light striking it.

A decrease in the amount of light hitting the sensor will cause an increase in the voltage on channel 0.

The LDR is useful for detecting larger changes in light or differentiating between night and day. The value read is a relative number rather than an absolute light intensity value.



**Thermistor** – The thermistor is a resistor that changes

resistance based on temperature.

A decrease in temperature will cause the voltage to increase on channel 1.

The thermistor is useful for detecting changes in temperature. Since the specification of the thermistor is not known so it is difficult to use it to measure the actual temperature. It is better suited for measuring relative changes in temperature and in some cases the readings can be correlated to a temperature by empirical testing.



Potentiometer – The 10K potentiometer is connected

between Vcc and Gnd with the wiper connected to channel 3.

Rotating the potentiometer will cause the voltage to vary between 0V and Vcc. Rotating the potentiometer CW decreases the voltage on channel 3.

The potentiometer can be used as a general purpose analog control input. For instance, the potentiometer can be read and the DAC output driving the LED can be set to match the read value.