

To Customers**Notification of appearance change of ETQP8M***JFA series Power Inductors****1. Reason of Change**

The outer dies (top and bottom) fitting position for press molding of core would be adjusted in order to improve productivity and life of press dies.

2. Part Number

Power Choke Coil ETQP8M***JFA series

3. Contents of Change

Parting lines occurring on the surface of the product.





image of product;



The product dimensions, electrical characteristics and reliability are the same,

There is only additional parting lines on the surface of the product.

There is no change from the current product with the characteristic reference value and the reliability guaranteed content.

4. Scheduled Date

- November 2019 onwards

5. Attached Documents

- Explanation of appearance change with parting line (1 page).

6. Expected Reply Date

- once there any concern, please contact us by the end of August 2019.

Best Regards