



# Product Change Notification

Current Date: 08-Jul-2020

## TE Connectivity

**Product Change Notification:** E-20-009164

**PCN Date:** 08-JUL-20

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
RDO 0434, GPL 214, Faston Receptacle 110 ,187, 250, 205 and 312 Series

**Description of Changes**  
Adding maximum tab gap force in CD drawing as per UL 310 standard.

**Reason for Changes:**  
Customer Request.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

**Note: This PCN contains only document changes, these changes do not affect the form, fit or function of the parts referenced.**

**Customer Drawing(s) Being Modified:**

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
<a href="#">1217027</a>	1217027-1	TYC1217027-1	D	
<a href="#">170032</a>	170032-2	TYC170032-2	U3	
<a href="#">170037</a>	170037-2	TYC170037-2	L1	
<a href="#">170183</a>	170183-2		E1	
<a href="#">170213</a>	170213-2		D1	
<a href="#">1742883</a>	1742883-1	TYC1742883-1	A6	
<a href="#">2238171</a>	2238171-3		A1	
<a href="#">2238172</a>	2238172-3		A1	
<a href="#">2238173</a>	2238173-3		A1	
<a href="#">2238174</a>	2238174-3		A1	
<a href="#">280232</a>	280232	TYC280232-0	W3	
<a href="#">41202</a>	41202		V	
<a href="#">41274</a>	41274	TYC41274	U1	
<a href="#">41411</a>	41411	TYC41411	P	
<a href="#">41412</a>	41412	TYC41412	P	
<a href="#">41532</a>	41532	TYC41532	AB	
<a href="#">41802</a>	41802	TYC41802	Z1	
<a href="#">42437</a>	42437-5	TYC42437-5	AD	
<a href="#">42452</a>	42452-2	TYC42452-2	AG	
<a href="#">42510</a>	42510-2		S	
<a href="#">42563</a>	42563-2	TYC42563-2	AD1	
<a href="#">42640</a>	42640-2	TYC42640-2	H	
<a href="#">42770</a>	42770-2	TYC42770-2	K2	
<a href="#">60621</a>	60621-1		D	
<a href="#">60851</a>	60851-1	TYC60851-1	AC	
<a href="#">61944</a>	61944-2	TYC61944-2	T	
<a href="#">63010</a>	63010-2	TYC63010-2	H1	
<a href="#">63306</a>	63306-1	TYC63306-1	R	
<a href="#">63316</a>	63316-5	TYC63316-5	T1	

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
<a href="#">63677</a>	63677-1	TYC63677-1	H	