KERN FS 2-100KSP1



Ready-assembled set consisting of premium force gauge FS 2 and external "S" measuring cell CS P1 for tensile and compressive force measurements



Category	
Brand	Sauter
Product categoriy	Force measurement
Product group	Force measuring device set
Product family	FS SP1
Magazina Custom	

Measuring System	
Default unit	Ν
Measuring range force [Max] (N)	100 kN
Readability force [d] (N)	20 N
Directions of force	tension compression
Measuring head measuring frequency	1000 Hz
Number of platforms / channels	2

Approval

CE mark

Display	
Display type	
Display resolution	

320×480 German English French

TFT, color

1

Languages of the user interface French Spanish Italian

Construction

Material display housing Material housing Plastics plastic

Mounting - force application	Threaded hole M33 × 3
Mounting - force dissipation	Threaded hole M33 \times 3
Dimensions load cell	125×175×50 mm
Functions	
Auto-off interval(s) in battery	selectable
mode/rechargeable battery mode	selectable
Peak function	\checkmark
Statistic function	1
Memory function	\checkmark
Interfaces	USB-Device
Power Supply	
Input voltage power supply /	100 V - 240 V, 50 / 60
power [Max]	Hz
Input voltage device / power [Max]	5 V, 1 A
Plug-in power supply type	USB including power supply
Supplied power supply	Battery & Power supply
Plug-in power supply / adapter for	Dattory a rower supply
countries - included with the	EURO
delivery	
Rechargeable battery charging time	8 h
Rechargeable battery operating	5 h
time - backlight on	011
Rechargeable battery operating	8 h
time - backlight off	
Battery / accumulator type	Li-lon
Battery connection	2-pole tub connector
Battery capacity	2.400 mAh
Battery voltage	3,7 V
Packing & Shipping	
Readability force [d] (N)	3 d
Net weight	7,02 kg
Shipping method	Parcel service
Net weight approx.	8 kg
Gross weight approx.	10 kg
Shipping weight	9,67 kg
Services (optional)	
Article number for factory calibration (tensile force)	961-166
Article number for factory	961-266
calibration (compressive force)	
Article number for factory calibration (tensile force/	961-366
compressive force)	/01/000
······································	1


KERN FS 2-100KSP1



Ready-assembled set consisting of premium force gauge FS 2 and external "S" measuring cell CS P1 for tensile and compressive force measurements

Pictograms

STANDARD



OPTION

