



29-Oct-2019

PCN #:P-19-018139

Subject:MQS TABLE SOCKET CONTACT

Description of Change: Manufacturing location change. Following Part Numbers will be transferred to produce in China Suzhou Plant 1 Part number is '5-962885-1' & 5-965906-1 2 New mold is NO.11-1935075 The new mold is not for delivery to AP area Asia-pacific please each sales colleague pay attention to this

Reason: Customer Request.Customer Request.The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN

Key Dates:

Product Affected

5-965906-1

5-962885-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.