

Product Change Notice

| | |
|-------------------------|--|
| Date: | February 4, 2022 |
| Overview: | Label change for select part numbers |
| Reason for Change: | Production location change |
| Affected Part No(s): | Please see part number listing on page 2 of this PCN |
| Design Change Detail: | Production of select part numbers is moving from Hungary to China, so the product labels will be updated accordingly. Please see page 2 of this PCN for the part number listing. |
| Effective Date: | Shipments beginning April 1, 2022 |
| Last Time Buy Deadline: | N/A |
| Pricing: | Per current price file |
| ebm-papst employee: | Jeannine Zenobi |
| Attachments: | Part number listing |
| Comments: | The entire production line is being moved so all product specifications will remain the same; only the manufacturing location on the label will change |

Affected Part Numbers

| | |
|-------------------|----------------|
| 4856ZWU | RL90-18/50-034 |
| 4656ZWU-924 | RL90-18/06-038 |
| 4656ZWU | 4656EAU-003 |
| 4656ZWU-963 | 4656ZWU-006 |
| 4656EZ-975 | 4656EZU |
| RG90-18/56 | 4656EA-021 |
| RET78-34/56-011 | 4586ZU-024 |
| RET85-42/56-017 | 4656ZU-025 |
| RET85-42/56-070 | 4856ZWU-065 |
| RG125-19/56 | 4660N |
| RG125-19/06 | 4650 NU |
| RER125-19/56 | 4656 NU |
| RER125-19/56U-164 | 8556 VWU |
| RER125-19/56U-169 | 3656 U-714 |
| 4656N | 3856 U-726 |
| RL90-18/50 | 4586 ZWU-843 |
| RL90-18/00 | 4606ZWU-845 |
| RL90-18/56 | 4656 ZH |
| RL90-18/06 | 4606 ZH |
| RL90-18/00-033 | 4606 ZWU-879 |

| | | |
|--------------------------------|---------------------------|-------------------------------|
| Form No: 1274 | Quality Record - No | Page 1 of 1 |
| Rev. - Orig, Released 08/28/14 | Retention Period - 1 year | Dept. Owner - Sales/Marketing |