



Montageanleitung KU 160 - KU 630

Pl-Nr.	Type		N.m		N.m maxi.					D mini. (CEI 664) L 1 L 2 L 3 N 400/690 V maxi.
076-160	KU 160	M 12	14 N.m	M 8	12 N.m	16... 95 mm ²	16... 95 mm ²	25 mm	13 mm	8 mm
076-250	KU 250	M 16	25 N.m	M 10	25 N.m	16... 185 mm ²	16... 185 mm ²	30 mm	16 mm	8 mm
076-400	KU 400	M 20	45 N.m	M 10	25 N.m	50... 240 mm ²	50... 300 mm ²	37,5 mm	20 mm	8 mm
076-630	KU 630			M 12	43 N.m	70... 300 mm ²	70... 300 mm ²	37,5 mm	24 mm	8 mm

Alle Angaben lt. Hersteller





M1-077-01

Günther Spelsberg GmbH + Co. KG • Im Gewerbepark 1
D-58579 Schalksmühle • Tel.: 0 23 55 / 8 92-0 • Fax.: 0 23 55 / 8 92-299
e-mail: info@spelsberg.de • Internet: www.spelsberg.de

Montageanleitung KU 160 - KU 630

Pl-Nr.	Type		N.m		N.m maxi.					D mini. (CEI 664) L 1 L 2 L 3 N 400/690 V maxi.
076-160	KU 160	M 12	14 N.m	M 8	12 N.m	16... 95 mm ²	16... 95 mm ²	25 mm	13 mm	8 mm
076-250	KU 250	M 16	25 N.m	M 10	25 N.m	16... 185 mm ²	16... 185 mm ²	30 mm	16 mm	8 mm
076-400	KU 400	M 20	45 N.m	M 10	25 N.m	50... 240 mm ²	50... 300 mm ²	37,5 mm	20 mm	8 mm
076-630	KU 630			M 12	43 N.m	70... 300 mm ²	70... 300 mm ²	37,5 mm	24 mm	8 mm

Alle Angaben lt. Hersteller



M1-077-01

Günther Spelsberg GmbH + Co. KG • Im Gewerbepark 1
D-58579 Schalksmühle • Tel.: 0 23 55 / 8 92-0 • Fax.: 0 23 55 / 8 92-299
e-mail: info@spelsberg.de • Internet: www.spelsberg.de