




Product Change Notification

Date Issued :	February 28, 2024	PCN Number :	514903
Reason for Change :	Change to Product		
Description of Change :	This notification is to inform you about changes that are being made to the part(s) as identified in the list. This change will not affect the Fit, Form, Function, or appearance of the parts. This does not affect the specification of the final assembly/finished good.		
Assessment of Change :	Dimension analysis		
Planned Implementation Date :	September 13, 2024		
Customer Sample Availability Date:	June 14, 2024		
Last date to request Samples by Customer : May 31, 2024			
Please note if Samples are not requested as per Customer Samples Request date, it may take additional 4-6 weeks to arrange Samples.			
Traceability Code Markings / Date :	Date code		

Before Picture

LVDS

■ Before Change




After Picture


After Change

LVDS

Contact Side



Latch Side



White jacket is pulled back so no interference with clips. This will call a small amount of the shield to be exposed at the edge of the clips as seen above.

RELEASED

Additional Information :

Overview

LVDS

- White jacket is pulled back to reduce interference with clips. This causes a small amount of the shield to be exposed at the edge of the clips, see After Change slide for more details.
 - This was done to make clip assembly easier and to reduce interference.
- Product Impact
 - No impact to fit, form, or function.
- Part Number Impact
 - Premoflex series 15022
 - See attached impacted parts list.

RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:514903
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 514903** " in the e-mail Subject line for faster response.

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com