# **Support Legs •** protected against slipping 22593.0405



## **Product Description**

The support legs are universally usable as adjustable legs.

In this version with a rubber cap, sensitive support surfaces are protected, and slipping is

The plate is screwed to the threaded pin and nut by a stainless steel fastening screw, and is also glued.

#### **Material**

### **Grub Screw**

• Steel, zinc-plated by galvanization, passivated

## Rubber cap

· Rubber, black

· Steel, zinc-coated by galvanisation, passivated, ISO 4032


· Steel, zinc-plated by galvanization, passivated


#### More information


#### **Further products**

· Support Legs

# **Drawing**







# **Order information**

| Dimensions                    |                |                |                |   | WS <sub>1</sub> | WS <sub>3</sub> | ă   | Art. No.   |
|-------------------------------|----------------|----------------|----------------|---|-----------------|-----------------|-----|------------|
| d <sub>1</sub>                | d <sub>2</sub> | I <sub>1</sub> | l <sub>2</sub> | t |                 |                 | _   |            |
|                               |                | [mm]           |                | • | [mm]            | [mm]            | [9] |            |
| with screw – picture 1, steel |                |                |                |   |                 |                 |     |            |
| 50                            | M12            | 100            | 11             | 2 | 17              | 18              | 139 | 22593.0405 |

Erwin Halder KG

www.halder.com Page 1 of 2

Published on: 8.7.2022

# Compliance

# **RoHS** compliant

Contains lead - compliant according to exceptions 6a / 6b / 6c

## Contains SVHC substances >0,1% w/w

Contains lead - SVHC list [REACH] as of 10.06.2022

#### **Contains Proposition 65 substances**



Lead can cause cancer and reproductive harm from exposure https://www.P65Warnings.ca.gov/

#### **Free from Conflict Minerals**

This product does not contain any substances designated as "conflict minerals" such as tantalum, tin, gold or tungsten from the Democratic Republic of Congo or adjacent countries.



Erwin Halder KG

www.halder.com Page 2 of 2

Published on: 8.7.2022