

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

**Software Early Problem Notification V1.0 for MC-ISAR_AS422_TC3xx:
issues in FEE driver affecting products TC3xx**

Software Early Problem Notification V1.0 for MC-ISAR_AS422_TC3xx: issues in FEE driver affecting products TC3xx

► **Products affected:**

Please refer to attached affected product list 1_cip05220

► **Detailed Change Information:**

Subject: Information about recent critical issues identified in productive releases of the MC-ISAR_AS422_TC3xx product.

Reason: New known issues.

Description: Old

New

■

- Software Early Problem Notification V1.0 for MC-ISAR_AS422_TC3xx (for details please refer to the SW EPN 4_cip05220 attached).

► **Product Identification:**

Not applicable (no change of product).

► **Impact of Change:**

Assessment in Application is required !

► **Attachments:**

Affected product list 1_cip05220
SW EPN V1.0 for MC-ISAR_AS422_TC3xx: 4_cip05220

► **Intended start of delivery:**

Not applicable

If you have any questions, please do not hesitate to contact your local Sales office.