

Before Picture

Before

The DU information communicated in the ERP is incorrect.

After Picture

After

The DU information in the ERP is updated. No impact to the products' Fit, Form and Function.
Part list is attached.

RELEASED

You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:513498 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 513498" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com